

EUROKARS SERVICES
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 ATTN.: MOTOR CLAIMS FAX :		NAME : SEET SER SIN		WIP :	
		ADDRESS : BEDOK		EXCESS :	
		470721		DATE: 29-Jun-20	
		TEL :			
VEH NO :	SKQ537Z	DATE IN :		CONTACT PERSON :	JOB
CHASSIS NO :		MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	BMW 520i	DATE REG.:		POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY	REVISED	PRICES
				\$ 1,628.00 ✓
1	REAR BUMPER <i>de -</i>	1	0	\$ 269.00
2	SIDE BRACKET RH <i>? XSVL</i>	1	0	\$ 269.00
3	SIDE BRACKET LH <i>? XSVL</i>	1	0	\$ 98.00
4	BOOTLID WEATHERSTRIP <i>cut X n n</i>	1	0	\$ 600.00 <i>60</i>
5	REAR BUMPER CLIPS <i>new</i>	10	0	\$ -
6		0	0	\$ -
	TOTAL PARTS <i>Less 5%</i>			\$ 2,864.00
				\$ -
	TOTAL PARTS COST			\$ 2,864.00
	Labour Description			
1	TO REPLACE REAR BUMPER, BOOTLID WEATHER STRIP & ALL DAMAGE PARTS . TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		<i>560</i> ✓	\$ 1,200.00 ✓
2	TO RESPRAY REAR BUMPER.		<i>560</i> ✓	\$ 600.00 ✓
3	TO TRANSFER THE REVERSE SENSORS.		<i>200</i> ✓	\$ 500.00 ✓
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		<i>150</i> ✓	\$ 250.00 ✓
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		<i>250</i> ✓	\$ 350.00 ✓
6	SUNDRIES.		NETT	\$ <i>20</i> / 50.00 ✓

P/P = \$3,343.60
 REPAIR DAYS = 3 DAYS

TOTAL LABOUR	\$ -	\$ 2,950.00
TOTAL PARTS	\$ -	\$ 2,864.00
TOTAL	\$ -	\$ 5,814.00
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -