

MFORTDELGRO ENGINEERING PTE LTD

PAIR ESTIMATE*

VEHICLE NO : SHD6556H

DATE: 27. Jun. 2020

MAKE : HYUNDAI

MODEL : i40

DOA: 26. Jun. 2020

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount			
1	Front Bumper Cover			\$1,052.20 <i>de</i>			
1	Front Bumper Side Bracket - RH			\$24.60 <i>re</i>			
1	Front Bumper Top Bracket - RH			\$22.40 <i>Xny</i>			
10	Front Bumper Clips		\$2.20	\$22.00 <i>re</i>			
1	Headlamp Support Panel			\$907.40 <i>Xny</i>			
1	Front Fender - RH			\$663.00 <i>R</i>			
1	Front Fender Shield - RH			\$174.90 <i>Xny</i>			
1	Headlamp - RH			\$1,388.00 <i>Xny</i>			
1	Front Wheel Cover - RH			\$107.10 <i>de</i>			
SUB TOTAL			1205.90	\$4,361.60			
LESS 20%			964.72	\$872.32			
DISCOUNTED TOTAL				\$3,489.28			
1	Advertisement - RHF Fender		100	\$100.00 <i>re</i> Nett			
<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party surveys on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				\$100.00			
				1	Panel Beating		\$600.00 <i>420</i>
				1	Spray Painting Charge		\$500.00 <i>400</i>
				1	Tuff Kote		\$80.00 <i>Xny</i>
				1	Wiring Charge		\$80.00 <i>50</i>
TOTAL LABOUR				\$1,260.00			
ESTIMATE TOTAL			1914.72	\$4,849.28			

Tanpin 97495745
-wp'
4/5 Resurvey after repair
tanpin@lkkhant.com
29/6/2020 3:00pm
02-03days

Larry 113

4/5 \$1550
2days #

850