

WHL PA, 30/6/20, 7-30pm, L/S, Ry AL sy

# PREMIER AUTOMOTIVE SERVICES PTE LTD

Steve (LKK)

4 dys

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

8322 8813

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

30-Jun-20

Steve chn @ LKK auto. com

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD1095 D

1 pc	Rear o/s door ✓ DD	\$ 791.00
1 pc	o/s rocker panel garnish X R	\$ 286.00
1 pc	Rear o/s wheel cover ✓ cut	\$ 116.00
1 pc	Rear bumper o/s side bracket X	\$ 29.00
1 pc	Rear bumper X R	\$ 696.00
		<hr/>
		\$ 1,918.00
	Less 10%	\$ 191.80
		<hr/>
		\$ 1,726.20

### S/NETT

1 set	o/s rocker panel garnish clips ✓ MC	\$ 38.00 10
1 set	o/s door stickers ✓ MC	\$ 100.00 380
1 pc	Rear o/s fender sticker ✓ MC	\$ 60.00 30
1 pc	Rear bumper clips ✓ MC	\$ 48.00 20
		<hr/>
	Sundry	\$ 50.00 30
	To check for rear o/s wheel alignment	\$ 80.00 60
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 X
	To refit old rear windscreen glass onto new moulding	\$ 120.00 X
	To refit inner components of the front & rear o/s doors onto new shell doors	\$ 300.00 50
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld & cut rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender, etc.	\$ 900.00 400
	To putty and spray painting on front o/s door, rear o/s door, o/s rocker panel garnish, rear o/s fender, rear bumper	\$ 1,000.00 800
	To apply rustproofing on the repaired and replaced panels.	\$ 180.00 X
		<hr/>
		\$ 8,019.00

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )  
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
UNFORESEEN DAMAGES.

LKK Auto Consultants hereby certify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer