

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

M/S NET LINK LEASING PTE LTD
71 WOODLANDS INDUSTRIAL PARK E9
#08-08
SINGAPORE 7507048

Contact : 85777022

TP Ching.
Shirley.

ESTIMATE

Repair Code : CLM16301

Date in : 30/06/2020

Vehicle Num. : GBH2483K

Model : TOYOTA HIACE DX 3.0 MANUAL

Chassis/Eng# : KDH2010212495/1KD2672730

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Deformed</i>	1	706.00	706.00 465.00
REAR BUMPER LOWER BRACKET <i>2 pieces bent</i>	4	45.10	180.40 90.20
REAR BUMPER SIDE RETAINER L/R <i>New</i>	2	66.10	✓ 132.20
REAR BUMPER STEP PANEL <i>Bent.</i>	1	299.80	✓ 299.80
REAR BUMPER STEP TOP COVER L/R <i>Not new</i>	2	39.80	X 79.60
REAR END PANEL (INNER) <i>Repair</i>	1	820.70	X 820.70
REAR END PANEL (OUTER) <i>Dented.</i>	1	743.00	✓ 743.00
REAR END PANEL L/R <i>Repair</i>	2	315.20	X 630.40
REAR END PANEL SIDE RUBBER STOPPER L/R <i>Not new</i>	2	68.10	X 136.20
REAR EXHAUST GASKET <i>Not new</i>	1	18.00	X 18.00
REAR EXHAUST PIPE <i>Not new</i>	1	442.00	X 442.00
REAR NUMBER PLATE LAMP L/R <i>Not new</i>	2	96.10	X 192.20
REAR SPARE TYRE CARRIAGE BRACKET <i>Bent</i>	1	243.10	✓ 243.10
REAR TAILGATE <i>Dented</i>	1	1950.00	✓ 1,950.00
REAR TAILGATE 'LOGO' EMBLEM <i>Not new</i>	1	71.60	✓ 71.60
REAR TAILGATE 'TOYOTA HIACE' STICKER <i>Not new</i>	1	58.00	✓ 58.00
REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R <i>Not new</i>	2	28.50	X 57.00
REAR TAILGATE INNER TRIM BOARD <i>Not new</i>	1	444.10	X 444.10

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

M/S NET LINK LEASING PTE LTD
71 WOODLANDS INDUSTRIAL PARK E9
#08-08
SINGAPORE 7507048

Contact : 85777022

ESTIMATE

Repair Code : CLM16301

Date in : 30/06/2020

Vehicle Num. : GBH2483K

Model : TOYOTA HIACE DX 3.0 MANUAL

Chassis/Eng# : KDH2010212495/1KD2672730

REAR TAILGATE LOCK STRIKER	<i>HPM</i>	1	70.20	<i>X</i>	70.20
REAR TAILGATE MECHANISM LOCK	<i>DND</i>	1	263.00	<i>✓</i>	263.00
REAR TAILGATE MECHANISM LOCK COVER	<i>cracked</i>	1	136.00	<i>✓</i>	136.00
REAR TAILGATE OUTER GARNISH	<i>int</i>	1	261.60	<i>✓</i>	261.60
REAR TAILGATE REMOTE CONTROL LOCK	<i>xtb new</i>	1	485.80	<i>X</i>	485.80
REAR TAILGATE WEATHER STRIP	<i>int</i>	1	387.60	<i>✓</i>	387.60
REAR TAILGATE WINDSCREEN GLASS	<i>int</i>	1	1257.10	<i>✓</i>	1,257.10
REAR TAILGATE WINDSCREEN SEAL	<i>new</i>	1	100.00	<i>✓</i>	100.00
REAR TAILLAMP L/R	<i>cracked</i>	2	354.80	<i>✓</i>	709.60
REAR TAILLAMP LOWER GARNISH L/R	<i>Regis</i>	2	157.00	<i>X</i>	314.00
REAR TAILLAMP LOWER GARNISH SIDE RETAINER L/R	<i>xtb new</i>	2	53.00	<i>X</i>	106.00
Subtotal before discount					11,295.20
Percentage discount 25%					2,823.80
Sub-total 1					8,471.40
REAR BUMPER CLIPS - SET	<i>new</i>	1	50.00	<i>30</i>	50.00
REAR TAILGATE '70KM' STICKER	<i>new</i>	1	25.00	<i>10</i>	25.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	<i>xtb</i>	1	50.00	<i>X</i>	50.00
REAR TAILGATE NUMBER PLATE	<i>new</i>	1	25.00	<i>X</i>	25.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

M/S NET LINK LEASING PTE LTD

71 WOODLANDS INDUSTRIAL PARK E9

#08-08

SINGAPORE 7507048

Contact : 85777022

ESTIMATE

Repair Code : CLM16301

Date in : 30/06/2020

Vehicle Num. : GBH2483K

Model : TOYOTA HIACE DX 3.0 MANUAL

Chassis/Eng# : KDH2010212495/1KD2672730

REAR TAILGATE WINDSCREEN SEALANT	<i>nm</i>	1	80.00	<i>60</i>	80.00
REAR TAILGATE WINDSCREEN SOLAR FILM	<i>nm</i>	1	500.00	<i>200</i>	500.00
REAR TAILLAMP CLIPS L/R - SET	<i>nm</i>	2	20.00	<i>30</i>	40.00
REAR TAILLAMP LOWER GARNISH CLIPS - SET	<i>nm nm</i>	1	20.00	<i>X</i>	20.00
REAR WINDSCREEN ART WORK STICKER	<i>Abel nm</i>	1	80.00	<i>X</i>	80.00
Subtotal before discount					870.00
Percentage discount 0%					0.00
Sub-total 2					870.00
Parts-total					9,341.40

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)	<i>30</i>	60.00
To remove, reinstall tailgate windscreen	<i>120</i>	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	<i>30</i>	100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	<i>1100</i>	1,200.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	<i>2430</i>	<i>X</i> 100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	<i>1000</i>	500.00
To apply anti-rust chemical on repaired and replaced panel.	<i>60</i>	80.00
To remove, reinstall tailgate mechanism and check for function	<i>✓</i>	80.00
Labour Total		3,270.00
Parts & Labour Total		12,611.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 8125.85

4/5: 6.5K

07 Days

(6.5K)