



KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfaction

Not Authorised
Runway Bypass
2-3 days

FAIRUSZA BINTE RAMLAH
14 Ang Mo Kio St 63
Block B
Singapore 569116

TP 200604
Date 30/6/2020
No of Page : 1/2

Registration No : SKH 7431X
Accident Date : 28-Jun-20
Our Ref : TP 200604

Model : Volkswagen Jetta 1.4
Chassis No: WVWZZZ16ZDM021302
Engine Capacity : 1390

S/No	Qty	Items	Unit Price	Amount
1	1	Rear bumper	\$ 1,388.75	\$ 1,388.75 ✓
2	2	Rear bumper retainer	\$ 110.40	\$ 220.80 X
3	1	Rear Bumper spoiler	\$ 686.75	\$ 686.75 ✓
4	1	Rear bumper reinforcement	\$ 606.50	\$ 606.50 ✓
5	1	LHS Taillamp	\$ 388.85	\$ 388.85 X
6	1	LHS Rear Bumper Reflector Light	\$ 66.55	\$ 66.55 ✓
7	1	RHS Rear Bumper Reflector Light	\$ 66.55	\$ 66.55 X
8	1	Rear Exhaust pipe	\$ 1,054.85	\$ 1,054.85 ✓

	\$ 4,479.60
-10%	\$ 447.96
Total for spare parts	\$ 4,031.64

Special Nett

1	1 set	Rear Bumper Clips	\$ 50.00	\$ 50.00 ✓
2	1	No. Plate with Casing	\$ 50.00	\$ 50.00 X
3	1 set	reverse sensor	\$ 250.00	\$ 250.00 down

Total for SP	\$ 350.00
Sub-Total for Parts :	\$ 4,381.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfaction

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.		200/ 600.00
2		To putty and spray paint on all accident damage parts and other accident affected areas		220/ 600.00
3		To check wiring system to facilitate repair and refit the same		100.00 15/
4		Apply rust proofing on the adjacent panels		~ 100.00 X
5		Remove and install reverse sensor		100.00 50/
6		To remove and refit exhaust pipe		100.00 7
TOTAL AMOUNT :				1,400.00
OVERALL COST :				5,781.64