

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

Stew (LKK)

8322 8813

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG: 200707743D GST REG: 200707743D

30-Jun-20

Stew@lkk.com

WL PL, 1/7/20, 1.30 pm

L/S, 3 days

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1123 G

1 pc	Front o/s head lamp	1 X N/A	\$	1,531.57 X
1 pc	Front bumper	1 X N/A	\$	811.11 /
1 pc	Front bumper emblem	1 X N/A	\$	27.80 X
1 pc	Front bumper o/s side bracket	1 X N/A	\$	32.51 /
1 pc	Front bumper o/s upper bracket	1 X N/A	\$	92.60 X
1 pc	Front bumper o/s support bracket	1 X N/A	\$	37.01 X
1 pc	Front o/s fender	1 X N/A	\$	514.02 /
1 pc	Front o/s fender inner shield	1 X N/A	\$	176.72 /
				\$ 3,223.34 1534.36
Less 20%				\$ 644.67 - 70%
				\$ 2,578.67 1227.48

S/NETT

1 set	Front bumper clips	1 X N/A	\$	48.00 30
1 pc	Front o/s fender sticker	1 X N/A	\$	30.00 20
1 set	Front o/s fender inner shield clips	1 X N/A	\$	28.00 15
				65
Sundry				\$ 50.00 X 30
To check wheel alignment				\$ 80.00 30 X
To focus/check front n/s & o/s head lamps				\$ 60.00 3 X
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.				\$ 180.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same				\$ 600.00 350
To putty and spray painting on front bumper, front o/s fender				\$ 400.00 /
To apply rustproofing on the repaired and replaced panels.				\$ 80.00 30
				\$ 4,134.67 819

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be received and approved by the Repairer
- Subject to final approval from the Repairer

Acknowledged by Repairer

Signature:

Date:

THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNSEEN DAMAGES.

P-1227.48

N-65

L-819

2122-48

L/S-1681.98

= 1700