

ASS. REC. BY:

REF:

146 / 2000684111ck

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

01 days

Res.: Yes or No

Lum Sum:

1.8.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 55967

Yr Regn:

01, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Prius

c.c

1798

Colour

M.P. White 1P

A/C:

Insured / Std / NI / NA

Sp. Reading

103288

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU 00.3079053

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F: Sailun

195/65R15

R:

GY

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

3

mm

L/Bal.

9

mm

L/Bal.

3

mm

D.O.A.

26/6/20

D.O.I.

30/6/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/8 8732.23 Cabins

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS: \$

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5596Z**AAD2006-077***Not Notified**Presony B4 paint**8732.23*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

30 JUN 2020**SHD 5596Z**

JTDKB3FU003079053

TOYOTA

PRIUS

26.6.2020

AIG

11/1/2019

| PART | | LIST | |
|------|---------------------------------|------|---------------|
| 1 | REAR BUMPER | \$ | Sn 442.60 X |
| 1 | REAR BUMPER RE-INFORCEMENT | \$ | N 332.70 X |
| 1 | REAR BUMPER TOWING COVER | \$ | Sn 15.40 X |
| 1 | GUARD, REAR BUMPER, CENTER | \$ | nd/w 576.30 ✓ |
| 1 | REAR BUMPER SIDE RETAINER LH | \$ | Sn 116.50 |
| 1 | REAR BUMPER SIDE RETAINER RH | \$ | Sn 117.70 |
| 1 | REAR TAILGATE | \$ | N 1,147.80 |
| 1 | REAR TAILGATE OUTER GARNISH | \$ | Sn 925.60 |
| 1 | REAR TAILGATE WEATHERSTRIP | \$ | Sn 372.30 |
| 1 | PANEL SUB-ASSY, BODY LOWER BACK | \$ | N 650.30 |
| 1 | TAILLAMP LOWER RH | \$ | Sn 502.00 |
| 1 | TAILLAMP UPPER RH | \$ | Sn 451.80 |
| 1 | REAR BUMPER SIDE RH | \$ | Sn 123.70 |
| 1 | REAR BUMPER SIDE LH | \$ | Sn 123.70 |
| 1 | TAILLAMP LOWER LH | \$ | Sn 502.00 |
| 1 | TAILLAMP UPPER LH | \$ | Sn 443.30 |
| 1 | COVER, DECK TRIM, REAR | \$ | Sn 126.70 |
| 1 | COVER, FLOOR UNDER, NO 1 | \$ | Sn 175.10 |
| 1 | COVER, FLOOR UNDER, NO 2 | \$ | Sn 241.90 |
| 1 | COVER, REAR FLOOR | \$ | Sn 229.90 |

| | | |
|--------------|-----------|-----------------|
| TOTAL | \$ | 7,617.30 |
| 25% | \$ | 1,904.33 |
| | \$ | 5,712.98 |

Special Nett

Trans-cab Auto Services Pte Ltd**AAD2006-077**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5596Z

| | | | | | | | |
|-------------|-----------------------------------|----|----|----------|---|---|--|
| 1SET | PARKING AID | \$ | Sn | 700.00 | } | X | |
| 1SET | REAR BUMPER CLIP | \$ | Nn | 69.00 | | | |
| 1 | REAR TAILGATE TOYOTA LOGO | \$ | Nn | 47.00 | | | |
| 1 | REAR TAILGATE WORDING 'PRIUS' | \$ | Nn | 52.90 | | | |
| 1 | REAR TAILGATE WORDING 'HYBRID' | \$ | Nn | 53.50 | | | |
| 1 | REAR TAILGATE STICKER 'TRANS-CAB' | \$ | Nn | 80.00 | | | |
| 1 | REAR TAILGATE STICKER '6555-3333' | \$ | Nn | 80.00 | | | |
| 1 | REAR BUMPER PROTECTOR | \$ | Nn | 120.00 | | | |
| 1 | REAR WHEEL RIM | \$ | Sn | 1,879.40 | | | |
| 1 | REAR TYRE 195/65/15 | \$ | Sn | 350.00 | | | |
| 1 | REAR WHEEL RIM COVER | \$ | Sn | 211.50 | | | |
| 1 | REAR RH BUMPER RETAINER CLIP | \$ | Nn | 38.00 | | | |
| 1 | REAR LH BUMPER RETAINER CLIP | \$ | Nn | 38.00 | | | |
| 1SET | TAILLAMP LOWER CLIP | \$ | Nn | 33.00 | | | |
| 1SET | TAILLAMP UPPER CLIP | \$ | Nn | 33.00 | | | |
| 1 | Rear Licence Plate with Moulding | \$ | Nn | 100.00 | | | |
| TOTAL | | \$ | | 3,885.30 | | | |
| TOTAL PARTS | | \$ | | 9,598.28 | | | |

LABOUR

| | | | |
|---|----|----------|-----|
| To transfer of Tailgate fittings, attachments and perform water seepage test. | \$ | 170.00 | X |
| To transfer of Rear Bumper fittings, attachments and perform water seepage test. | \$ | 170.00 | X |
| To transfer of rear end panel fittings, attachment and perform water seepage test. | \$ | 170.00 | X |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 6,000.00 | 80% |

Trans-cab Auto Services Pte Ltd**AAD2006-077**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5596Z

| | | | |
|---|-----------|------------------|-------------|
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair. | \$ | <i>nn</i> 380.00 | <i>X</i> |
| To Rust-Proofing Of The Affected Areas. | \$ | <i>↪</i> 170.00 | <i>X</i> |
| To reinstall rear bumper parking sensor. | \$ | <i>↪</i> 170.00 | <i>X</i> |
| To transfer of tire, rim and on wheel balancing. | \$ | <i>↪</i> 170.00 | <i>X</i> |
| To Check Electrical Lighting Concerned. | \$ | <i>↪</i> 170.00 | <i>X</i> |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. | \$ | <i>↪</i> 380.00 | <i>X</i> |
| Putty And Spray Painting Of The Affected Portion. | \$ | 6,000.00 | <i>2201</i> |
| TOTAL | \$ | 13,950.00 | |
| Over All Total | \$ | 23,548.28 | |

(PART-BY-PART) Repair Days*20 Days**1 day*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|---|--------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Company |
| Owner ID: | 878K |
| Vehicle Details | |
| Vehicle No.: | SHD5596Z |
| Vehicle to be Exported: | Yes |
| Intended Deregistration Date: | 26 Jun 2020 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | PRIUS 5DR HATCHBACK (AUTO) |
| Primary Colour: | Red |
| Manufacturing Year: | 2018 |
| Engine No.: | 2ZR2B97855 |
| Chassis No.: | JTDKB3FU003079053 |
| Maximum Power Output: | 90.0 kW (120 bhp) |
| Open Market Value: | \$26,605.00 |
| Original Registration Date: | 11 Jan 2019 |
| First Registration Date: | 11 Jan 2019 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$14,247.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 10 Jan 2027 |
| PARF Rebate Amount: | \$10,685.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 10 Jan 2027 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 8 |
| PQP Paid: | \$20,838.00 |
| COE Rebate Amount: | \$16,670.00 |
| Total Rebate Amount: | \$27,355.00 |
| Message | |
| Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. | |

The information contained herein is correct as at 26 Jun 2020

OK