

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5596Z**

AAD2006-077

*Not Authorised**Presumably B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

30 JUN 2020

**SHD 5596Z**

JTDKB3FU003079053

TOYOTA

PRIUS

26.6.2020

**AIG**

11/1/2019

	PART
1	REAR BUMPER
1	REAR BUMPER RE-INFORCEMENT
1	REAR BUMPER TOWING COVER
1	GUARD, REAR BUMPER, CENTER
1	REAR BUMPER SIDE RETAINER LH
1	REAR BUMPER SIDE RETAINER RH
1	REAR TAILGATE
1	REAR TAILGATE OUTER GARNISH
1	REAR TAILGATE WEATHERSTRIP
1	PANEL SUB-ASSY, BODY LOWER BACK
1	TAILLAMP LOWER RH
1	TAILLAMP UPPER RH
1	REAR BUMPER SIDE RH
1	REAR BUMPER SIDE LH
1	TAILLAMP LOWER LH
1	TAILLAMP UPPER LH
1	COVER, DECK TRIM, REAR
1	COVER, FLOOR UNDER, NO 1
1	COVER, FLOOR UNDER, NO 2
1	COVER, REAR FLOOR

	LIST
\$	SH 442.60 X
\$	R 332.70 X
\$	SH 15.40 X
\$	nd/Lt 576.30 ✓
\$	SH 116.50
\$	SH 117.70
\$	R 1,147.80
\$	SH 925.60
\$	SH 372.30
\$	R 650.30
\$	SH 502.00
\$	SH 451.80
\$	SH 123.70
\$	SH 123.70
\$	SH 502.00
\$	SH 443.30
\$	SH 126.70
\$	SH 175.10
\$	SH 241.90
\$	SH 229.90

TOTAL	\$	7,617.30
25%	\$	1,904.33
	\$	5,712.98

**Special Nett**

**Trans-cab Auto Services Pte Ltd****AAD2006-077**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5596Z**

1SET	PARKING AID	\$	Sn	700.00	}	X	
1SET	REAR BUMPER CLIP	\$	Nn	69.00			
1	REAR TAILGATE TOYOTA LOGO	\$	Nn	47.00			
1	REAR TAILGATE WORDING 'PRIUS'	\$	Nn	52.90			
1	REAR TAILGATE WORDING 'HYBRID'	\$	Nn	53.50			
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	Nn	80.00			
1	REAR TAILGATE STICKER '6555-3333'	\$	Nn	80.00			
1	REAR BUMPER PROTECTOR	\$	Nn	120.00			
1	REAR WHEEL RIM	\$	Sn	1,879.40			
1	REAR TYRE 195/65/15	\$	Sn	350.00			
1	REAR WHEEL RIM COVER	\$	Sn	211.50			
1	REAR RH BUMPER RETAINER CLIP	\$	Nn	38.00			
1	REAR LH BUMPER RETAINER CLIP	\$	Nn	38.00			
1SET	TAILLAMP LOWER CLIP	\$	Nn	33.00			
1SET	TAILLAMP UPPER CLIP	\$	Nn	33.00			
1	Rear Licence Plate with Moulding	\$	Nn	100.00			
TOTAL		\$		3,885.30			
TOTAL PARTS		\$		9,598.28			

**LABOUR**

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	Sal

**Trans-cab Auto Services Pte Ltd****AAD2006-077**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5596Z**

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To Rust-Proofing Of The Affected Areas.	\$	↪ 170.00	X
To reinstall rear bumper parking sensor.	\$	↪ 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	↪ 170.00	X
To Check Electrical Lighting Concerned.	\$	↪ 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	↪ 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	2201
<b>TOTAL</b>	<b>\$</b>	<b>13,950.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>23,548.28</b>	

**(PART-BY-PART) Repair Days**~~20 Days~~

1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: