

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0448/2020/NS
Date 22-Jul-20
Service Advisor Glory Tan
Pages 1 of 1
Regn No SKS 211 C
Model No Audi A6 1.8 TFSI S TRONIC

Quantity	Description		Unit Price	Amount
<u>Parts</u>				
1	Rear subframe <i>Best</i>	\$	3,330.00	✓ 2664
2	Bolts for rear subframe <i>new</i>	\$	74.00	✓ 806.4
3	Fuel tank assy <i>int</i>	\$	5,627.00	✓ 4501.60
4	Seal ring for fuel tank assy <i>new</i>	\$	92.00	✓ 73.60
5	Heat shield for tunnel <i>Dented</i>	\$ <i>nm x</i>	198.00	✓
<u>Labours</u>				
1	To remove and reinstall exhaust system and rear suspension assy. Renew accordingly.	s/n \$	2,400.00	✓ 2400
2	To remove and renew fuel tank assy.	s/n	600.00	✓ 600
3	To remove and reinstall interior floor carpet, centre console, front seats, rear seats, back rests and hat trays to facilitate repairing of floor pan.	s/n \$	1,800.00	✓ X
4	To weld and repair floor pan.	\$	1,000.00	250 X
5	To respray floor pan.	\$	1,000.00	550 X
TOTAL			\$	16,121.00

For Premium Automobiles Pte Ltd

Adrian Ling
23/07/20

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 39193

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0448/2020/NS
Date : 26-Jun-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Au Kheng Sheng
Address : Blk 79 Marine Drive
Singapore 440079
Telephone : HP +65 96954805
Type of Claim : Own Damage Claims
Policy No. : 1800039616-01
Vehicle No : **SKS 211 C**
Model Code : Audi A6 1.8 TFSI S TRONIC
Model / Year : 16/4/2018
Engine No : CYG 020047
Chassis No : WAUZZZ4G5HN114239
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 20-Jun-20
Place of Accident : Hougang Ave 3 Towards Eunos Link

Premium Automobiles

85, LBN Road, Singapore 408699
Tel: (65) 2321 1181 Fax: (65) 2321 1181

Telefax

Estimated Labour Charges for Accident Vehicle: SKS 211 C

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horn, outside temperature sensor, headlight washer assy and front parking aid. S/N \$	480.00	X
2	To remove and reinstall front suspension assy with subframe. Inspect for damages and renew if necessary. S/N \$	2,400.00	✓
3	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed. S/N \$	1,200.00 250	500
4	To respray front bumper and front bumper spoiler. S/N \$	2,000.00 300	✓
5	To remove and renew both rear exhaust silencer and centre silence. To align to position. S/N \$	480.00	✓
6	To carry out wheel alignment. S/N \$	240.00	✓
7	To carry out diagnostic check. S/N \$	192.00	✓
TOTAL LABOUR CHARGES		: \$ 6,992.00	

Premium Automobiles

1101, KUALA LUMPUR, MALAYSIA
Tel: 03-2612 0000 FAX: 03-2612 0001

Telefax

Material List for Accident Vehicle Regn No. SKS 211 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>New</i>	\$ 2,877.00	+
2	FRONT BUMPER FIXING PARTS <i>New</i>	\$ 511.00	+
3	FRONT BUMPER GRILLE - LOWER CENTRE <i>New</i>	\$ 120.00	+
4	LOCKING CLIP <i>New</i>	14 \$ 52.00	+
5	FRONT BUMPER SPOILER <i>Dehd</i>	\$ 889.00	✓ 711.20
6	RADIATOR GRILLE <i>New</i>	\$ 1,820.00	+
7	RADIATOR GRILLE COVER <i>New</i>	\$ 34.00	+
8	SUPPORT FRAME <i>Dehd</i>	\$ 3,660.00	✓ 2922
9	ASSEMBLY CARRIER STRUT BRACE <i>New</i>	\$ 182.00	+
photo 10	STEERING GEAR <i>Damaged</i>	\$ 6,388.00	✓ 5110.40
11	ANTI ROLL BAR <i>Best</i>	\$ 467.00	✓ 392
12	ANTI ROLL BAR RUBBER BUSH <i>New New</i>	\$ 13.00	✓ 10.24
13	ENGINE UNDERSHIELD - FRONT / REAR <i>torn</i>	2 \$ 1,196.00	✓ 956.80
14	UNDERBODY TRIM - LH <i>New</i>	\$ 138.00	+
15	UNDERBODY TRIM - LH / RH <i>RH torn</i>	2 \$ 630.00	325 302.40
16	UNDERBODY TRIM - LH / RH <i>New</i>	2 \$ 356.00	X
17	REAR SILENCER - LH <i>New</i>	\$ 1,216.00	+
18	REAR SILENCER DUAL CLIP <i>New New</i>	\$ 55.00	X
19	REAR SILENCER BRACKET <i>New</i>	\$ 54.00	X
20	REAR SILENCER - RH <i>Dehd New</i>	\$ 1,216.00	X H.S.
SUB TOTAL SPARE PARTS		: \$ 21,874.00	

Premium Automobiles

100 Hill Street, Singapore 416054
Tel: 3392 2121 Fax: 3394 1380

Telefax

Material List for Accident Vehicle Regn No. SKS 211 C

		Damaged Parts & Prices	
S/N	Parts Description	S/Nett	Remarks
21	REAR SILENCER DUAL CLIP <i>use ne</i>	\$ 55.00	*
22	REAR SILENCER BRACKET <i>use ne</i>	\$ 54.00	*
23	CENTRE SILENCER <i>Dested</i>	\$ 920.00	? <i>772.40</i>
24	CENTRE SILENCER DUAL CLIP <i>use ne</i>	\$ 57.00	✓ <i>46.32</i>
25	CENTRE SILENCER DUAL CLIP <i>use ne</i>	2 \$ 109.00	✓ <i>89.92</i>
26	FRONT BUMPER CLOSING ELEMENT <i>use</i> MISSING	\$ 206.00	+ <i>172.80</i>
27	FRONT NO PLATE <i>use</i>	S/N \$ 60.00	+ <i>58.80 58.80</i>
28	SUNDRIES <i>use</i>	\$ 400.00	→ <i>275.44, 334.24</i>
TOTAL SPARE PARTS		:	\$ 23,735.00
TOTAL LABOUR CHARGES		:	\$ 6,992.00
GRAND TOTAL		:	\$ 30,727.00

All charges are not inclusive of GST

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name : Admin
Surveyed Date : 07/07/201
Authorised Date : Admin
Excess Cost : Repairing 23/07/20
Liability :
Remarks : Not Authorised, 06 days + ~~7 days~~
HLS
09 Days HLS

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 39193

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0448/2020/NS
Date : 26-Jun-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,

We took 9 days to repair this car.
17/12/2020 - Carrine

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Au Kheng Sheng
Address : Blk 79 Marine Drive
Singapore 440079
Telephone : HP +65 96954805
Type of Claim : Own Damage Claims
Policy No. : 1800039616-01
Vehicle No : **SKS 211 C**
Model Code : Audi A6 1.8 TFSI S TRONIC
Model / Year : 16/4/2018
Engine No : CYG 020047
Chassis No : WAUZZZ4G5HN114239
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 20-Jun-20
Place of Accident : Hougang Ave 3 Towards Eunos Link

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKS 211 C

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horn, outside temperature sensor. headlight washer assy	S/N \$	480.00	
2	To remove and reinstall front suspension assy with subframe. Inspect for damages and renew if necessary.	S/N \$	2,400.00	\$ 2,400.00
3	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.	\$	1,200.00	\$ 500.00
4	To respray front bumper and front bumper	\$	2,000.00	\$ 300.00
5	To remove and renew both rear exhaust silencer and centre silence. To align to	S/N \$	480.00	\$ 480.00
6	To carry out wheel alignment.	S/N \$	240.00	\$ 240.00
7	Supplementary	\$	6,800.00	\$ 3,000.00
8	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 13,792.00	\$ 7,112.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 211 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 2,877.00	
2	FRONT BUMPER FIXING PARTS	\$ 511.00	
3	FRONT BUMPER GRILLE - LOWER CENTRE	\$ 120.00	
4	LOCKING CLIP	14 \$ 52.00	
5	FRONT BUMPER SPOILER	\$ 889.00	\$ 711.20
6	RADIATOR GRILLE	\$ 1,820.00	
7	RADIATOR GRILLE COVER	\$ 34.00	
8	SUPPORT FRAME	\$ 3,660.00	\$ 2,928.00
9	ASSEMBLY CARRIER STRUT BRACE	\$ 182.00	
10	STEERING GEAR	\$ 6,388.00	\$ 5,110.40
11	ANTI ROLL BAR	\$ 467.00	\$ 392.00
12	ANTI ROLL BAR RUBBER BUSH	\$ 13.00	\$ 10.24
13	ENGINE UNDERSHIELD - FRONT / REAR	2 \$ 1,196.00	\$ 956.80
14	UNDERBODY TRIM - LH	\$ 138.00	
15	UNDERBODY TRIM - LH / RH	2 \$ 630.00	\$ 504.00
16	UNDERBODY TRIM - LH / RH	2 \$ 356.00	
17	REAR SILENCER - LH	\$ 1,216.00	
18	REAR SILENCER DUAL CLIP	\$ 55.00	
19	REAR SILENCER BRACKET	\$ 54.00	
20	REAR SILENCER - RH	\$ 1,216.00	
SUB TOTAL SPARE PARTS		: \$ 21,874.00	\$ 10,411.04

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 211 C

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remarks
21	REAR SILENCER DUAL CLIP	c/f	\$ 55.00	\$ 10,411.04
22	REAR SILENCER BRACKET		\$ 54.00	
23	CENTRE SILENCER		\$ 920.00	\$ 772.40
24	CENTRE SILENCER DUAL CLIP		\$ 57.00	\$ 46.32
25	CENTRE SILENCER DUAL CLUP	2	\$ 109.00	\$ 89.92
26	FRONT BUMPER CLOSING ELEMENT		\$ 206.00	\$ 172.80
27	FRONT NO PLATE	S/N	\$ 60.00	
28	SUPPLEMENTARY		\$ 9,321.00	\$ 7,319.84
29	SUPPLEMENTARY		\$ 73.50	\$ 58.80
30	SUNDRIES		\$ 400.00	\$ 275.44
TOTAL SPARE PARTS		:	\$ 33,129.50	\$ 19,146.56
TOTAL LABOUR CHARGES		:	\$ 13,792.00	\$ 7,112.00
GRAND TOTAL		:	\$ 46,921.50	\$ 26,258.56

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0448/2020/NS
Date 22-Jul-20
Service Advisor Clory Tan
Pages 1 of 1
Regn No SKS 211 C
Model No Audi A6 1.8 TFSI S TRONIC

Quantity	Description		Unit Price	Amount
Parts				
1	Rear subframe	\$	3,330.00	\$ 2,664.00
2	Bolts for rear subframe	\$	74.00	\$ 80.64
3	Fuel tank assy	\$	5,627.00	\$ 4,501.60
4	Seal ring for fuel tank assy	\$	92.00	\$ 73.60
5	Heat shield for tunnel	\$	198.00	
				<u>\$ 7,319.84</u>
Labours				
1	To remove and reinstall exhaust system and rear suspension assy. Renew accordingly.	s/n \$	2,400.00	\$ 2,400.00
2	To remove and renew fuel tank assy.	s/n	600.00	\$ 600.00
3	To remove and reinstall interior floor carpet, centre console, front seats, rear seats, back rests and hat trays to facilitate repairing of floor pan.	s/n \$	1,800.00	
4	To weld and repair floor pan.	\$	1,000.00	
5	To respray floor pan.	\$	1,000.00	
				<u>\$ 3,000.00</u>
TOTAL			<u>\$ 16,121.00</u>	<u>\$10,319.84</u>

For Premium Automobiles Pte Ltd

Authorised Signature