

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 39713

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/456/2020/NS
Date : 30-Jun-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

3 days - ok - jb - 13 Aug 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Prashanth Rao Pejavar
Address : 6B Hougang Street 11
#07-19
Singapore 534083
Telephone : HP +65 96254004
Type of Claim : Own Damage Claims
Policy No. : 1900252286
Vehicle No : **SGE 8116 M**
Model Code : Audi Q3 1.4 TFSI S TONIC
Model / Year : Nov-19
Engine No : CZD 886615
Chassis No : WAUZZZF533L1015705
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-May-20
Place of Accident : Mustafa Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGE 8116 M

S/N Nature of Jobs		Estimated Charges		Surveyor's commendations	
1	To remove and transfer rear lid's convenience locl system, wire harness for tail lights and rear wiper assy.	S/N	\$ 480.00	\$	480.00
2	To renew rear windscreen to facilitate rear lid renewal.	S/N	\$ 480.00	\$	480.00
3	To install rear windscreen solar film.	S/N	\$ 400.00	\$	400.00
4	To dismantle and renew rear lid. Re-organise rear crash management components. Reinstall all parts removed.		\$ 1,200.00	\$	500.00
5	To respray rear lid.		\$ 1,500.00	\$	550.00
6	To carry out diagnostic check.	S/N	\$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 4,252.00	\$	2,602.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGE 8116 M

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	Remarks
1	REAR LID	\$ 3,305.00	\$ 2,644.00
2	PACKING ADHESICE	\$ 18.00	\$ 14.40
3	REAR LID ATTACHMENT PARTS	\$ 354.00	
4	REAR LID LOCK	\$ 232.00	
5	REAR LID STRIKER PLATE	\$ 63.00	
6	LID LOCK PUSH BUTTON	\$ 1,267.00	
7	AUDI EMBLEM	\$ 117.00	\$ 93.60
8	Q3 INSCRIPTION	\$ 90.00	\$ 72.00
9	REAR WINDSCREEN	\$ 901.00	\$ 720.80
10	PRIMER	\$ 19.00	\$ 15.20
11	REAR SPOILER - LH / RH	2 \$ 398.00	\$ 318.40
12	REAR WINDSCREEN SEALANT	S/N \$ 200.00	\$ 200.00
13	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS CHARGES		: \$ 7,264.00	\$ 4,078.40
TOTAL LABOUR CHARGES		: \$ 4,252.00	\$ 2,602.00
GRAND TOTAL		: \$ 11,516.00	\$ 6,680.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant