

Not Authorized
Lamp &

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 214J

AAD2006-083

Vehicle No.:

Chassis No.:

30 JUN 2020

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 214J

VF1ABL15AUC282288

RENAULT

LATITUDE

26.6.2020

FCIL

16-10-15

	PART
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER BRACKET FRT RH
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	BUMPER BEAM FRT
1	HEADLAMP RH
1	HEADLAMP PANEL FRT RH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER BRACKET LOWER RH
1	FENDER BRACKET FRT RH
1	FENDER INSULATOR RH
1	TOW COVER FRT
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	FRAME FULL SUPPORT PANEL
1	FRAME FULL SUPPORT BRACKET
1	BONNET
1	BONNET INSULATOR
1	BONNET STRUT RH

	LIST	
\$	mycom	747.20 ✓
\$	SL	344.70 X
\$	SL	186.50 X
\$	SL	394.68 X
\$	SL	101.40 ✓
\$	SL	10.70
\$	SL	292.50
\$	SL	147.00
\$	SL	207.21 X
\$	R	663.70
\$	SL	743.60
\$	R	128.30
\$	B	437.10 ✓
\$	CMA	191.40 ✓
\$	SL	11.80
\$	R	106.40
\$	SL	66.30
\$	SL	60.90
\$	SL	969.90
\$	SL	225.36 X
\$	SL	686.00
\$	R	592.70
\$	R	41.60
\$	R	1,312.70
\$	SL	294.30
\$	SL	53.30

Trans-cab Auto Services Pte Ltd

AAD2006-083

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 214J

1	BONNET HINGE RH	\$	R	237.40	X
1	LOWER ARM RH L70Y	\$		192.70	?
1	KNUCKLE ARM RH L70Y	\$		481.50	?
1	ABSORBER FRT RH L70Y	\$		274.10	?
1	DRIVESHAFT RH	\$	R	1,355.70	X
1	KNUCKLE HUB+BEARING RH	\$		272.30	?
1	STABILIZER BAR FRT	\$	Sh	427.90	X
1	WIPER RESERVOIR MOTOR	\$	Sh	82.60	X
1	WIPER RESERVOIR	\$	Sh	179.60	X
1	WIPER RESERVOIR NECK	\$	Sh	29.30	X
1	ROCKER PANEL OUTER RH	\$	R	1,184.99	X
1	DOOR PANEL FRT RH	\$	R	2,844.66	X
1	DOOR HINGE UPPER FRT RH	\$	R	274.50	}
1	DOOR HINGE LOWER FRT RH	\$	R	300.55	
1	DOOR CHECK FRT RH	\$	Sh	194.77	
1	DOOR REGULATOR FRT RH	\$	Sh	505.19	
1	DOOR REGULATOR MOTOR FRT RH	\$	Sh	796.46	
1	DOOR WEATHERSTRIP FRT RH	\$	Sh	410.27	
1	DOOR MOULDING FRT RH	\$	Sh	291.27	
1	DOOR SEAL FRT RH	\$	Sh	72.82	
1	DOOR SEAL LOWER FRT RH	\$	Sh	91.17	
1	DOOR HANDLE OUTER FRT RH	\$	Sh	477.76	}
1	DOOR MIRROR ASSY RH	\$	Sh	1,483.40	
TOTAL		\$		21,478.16	
10%		\$		2,147.82	
		\$		19,330.35	

Special Nett

1	BUMPER CLIP FRT	\$	na	75.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	na	40.00	X
1	BUMPER RETAINER CLIP FRT RH	\$	na	45.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	na	15.00	X
1	BUMPER GRILLE LOWER CLIP	\$	na	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	X

Trans-cab Auto Services Pte Ltd

AAD2006-083

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 214J

2	FRAME FULL SUPPORT PANEL NUT	\$	nn	25.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	X
1	WHEELARCH CLIP FRT RH	\$	nn	45.00	—
1	FRONT RENAULT TYRE	\$	nn	300.00	708nn—
1SET	Front licence plate with holder	\$	nn	120.00	X
1	FRONT RENAULT TYRE RIM	\$	nn	380.00	—
1SET	RADIATOR GRILLE SCREW	\$	nn	35.00	X
1SET	RADIATOR GRILLE FRAME CLIP	\$	nn	55.00	X
1	Front Door Sticker "Trans-Cab"	\$	nn	80.00	608nn—
1	Front Door Sticker "Classic"	\$	nn	80.00	155nn—
1SET	ROCKER PANEL CLIP	\$	nn	45.00	X

TOTAL \$ 1,509.00**TOTAL PARTS \$ 20,839.35****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 6,000.00 500

To transfer of bonnet fittings, attachment and perform water seepage test.

\$ nn 170.00 X

Putty and spray painting of the affected portion.

\$ 6,000.00 660

To check steering geometry and computer wheel alignment

\$ 220.00 60

To transfer of front fender fittings, attachment and perform water seepage test.

\$ nn 170.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ nn 380.00 X

Trans-cab Auto Services Pte Ltd

AAD2006-083

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 214J

To Check Electrical Lighting Concerned.	\$	170.00	201
To rust-proofing of the affected areas.	\$	170.00	301
To check ABS and brake efficiency, final checking and testing.	\$	nn 380.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	170.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	?
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	201
To transfer of door fittings, attachment and perform water seepage test.	\$	nn 170.00	X
TOTAL	\$	14,930.00	
Over All Total	\$	35,769.35	

LUMP SUM (REPAIR DAY)~~20 DAYS~~

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: