

ASS. REC. BY:

REF:

1702/20006849/ke

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD214J

Yr Regn:

10, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Renault Latitude c.c.

1995

Colour

M-White/Red

A/C:

Insured / Std / NI / NA

Sp. Reading

691030

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL 154UC 282288

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Sailun

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

26/6/20

D.O.I.

30/6/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt body

The U/C / Chassis frame / Body structure affected due to collision.

Date / Time

Action / Instruction

11 Lm & 2700k Cabin

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Not Authorized
Lamp 82700h

Trans-cab Auto Services Pte Ltd

AAD2006-083

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 214J

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

30 JUN 2020

SHD 214J

VF1ABL15AUC282288

RENAULT

LATITUDE

26.6.2020

FCIL

16-10-15

PART	
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER BRACKET FRT RH
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	BUMPER BEAM FRT
1	HEADLAMP RH
1	HEADLAMP PANEL FRT RH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER BRACKET LOWER RH
1	FENDER BRACKET FRT RH
1	FENDER INSULATOR RH
1	TOW COVER FRT
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	FRAME FULL SUPPORT PANEL
1	FRAME FULL SUPPORT BRACKET
1	BONNET
1	BONNET INSULATOR
1	BONNET STRUT RH

LIST	
\$	mycom 747.20 ✓
\$	SL 344.70 X
\$	SL 186.50 X
\$	SL 394.68 X
\$	SL 101.40 ✓
\$	SL 10.70
\$	SL 292.50
\$	SL 147.00
\$	SL 207.21 X
\$	R 663.70
\$	SL 743.60
\$	R 128.30
\$	R 437.10 ✓
\$	CMS 191.40 ✓
\$	SL 11.80
\$	R 106.40
\$	SL 66.30
\$	SL 60.90
\$	SL 969.90
\$	SL 225.36 X
\$	SL 686.00
\$	R 592.70
\$	R 41.60
\$	R 1,312.70
\$	SL 294.30
\$	SL 53.30

Trans-cab Auto Services Pte Ltd**AAD2006-083**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 214J

1	BONNET HINGE RH	\$	R	237.40	X
1	LOWER ARM RH L70Y	\$	Sn	192.70	X
1	KNUCKLE ARM RH L70Y	\$	Sn	481.50	X
1	ABSORBER FRT RH L70Y	\$	Sn	274.10	X
1	DRIVESHAFT RH	\$	R	1,355.70	X
1	KNUCKLE HUB+BEARING RH	\$	nn	272.30	X
1	STABILIZER BAR FRT	\$	Sn	427.90	X
1	WIPER RESERVOIR MOTOR	\$	Sn	82.60	X
1	WIPER RESERVOIR	\$	Sn	179.60	X
1	WIPER RESERVOIR NECK	\$	Sn	29.30	X
1	ROCKER PANEL OUTER RH	\$	R	1,184.99	X
1	DOOR PANEL FRT RH	\$	R	2,844.66	X
1	DOOR HINGE UPPER FRT RH	\$	R	274.50	X
1	DOOR HINGE LOWER FRT RH	\$	R	300.55	
1	DOOR CHECK FRT RH	\$	Sn	194.77	
1	DOOR REGULATOR FRT RH	\$	Sn	505.19	
1	DOOR REGULATOR MOTOR FRT RH	\$	Sn	796.46	
1	DOOR WEATHERSTRIP FRT RH	\$	Sn	410.27	
1	DOOR MOULDING FRT RH	\$	Sn	291.27	
1	DOOR SEAL FRT RH	\$	Sn	72.82	
1	DOOR SEAL LOWER FRT RH	\$	Sn	91.17	
1	DOOR HANDLE OUTER FRT RH	\$	Sn	477.76	
1	DOOR MIRROR ASSY RH	\$	Sn	1,483.40	

TOTAL \$ 21,478.16**10% \$ 2,147.82****\$ 19,330.35****Special Nett**

1	BUMPER CLIP FRT	\$	nn	75.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	nn	40.00	X
1	BUMPER RETAINER CLIP FRT RH	\$	nn	45.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	nn	15.00	X
1	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	X

Trans-cab Auto Services Pte Ltd**AAD2006-083**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 214J

2	FRAME FULL SUPPORT PANEL NUT	\$	nn	25.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	X
1	WHEELARCH CLIP FRT RH	\$	nn	45.00	✓
1	FRONT RENAULT TYRE	\$	nn	300.00	708sn - 210sn
1SET	Front licence plate with holder	\$	nn	120.00	X
1	FRONT RENAULT TYRE RIM	\$	nn	380.00	✓
1SET	RADIATOR GRILLE SCREW	\$	nn	35.00	X
1SET	RADIATOR GRILLE FRAME CLIP	\$	nn	55.00	X
1	Front Door Sticker "Trans-Cab"	\$	nn	80.00	608sn -
1	Front Door Sticker "Classic"	\$	nn	80.00	15sn -
1SET	ROCKER PANEL CLIP	\$	nn	45.00	X
TOTAL		\$		1,509.00	

TOTAL PARTS	\$	20,839.35
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 6,000.00 500d

To transfer of bonnet fittings, attachment and perform water seepage test.

\$ nn 170.00 X

Putty and spray painting of the affected portion.

\$ 6,000.00 660d

To check steering geometry and computer wheel alignment

\$ 220.00 60d

To transfer of front fender fittings, attachment and perform water seepage test.

\$ nn 170.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ nn 380.00 X

Trans-cab Auto Services Pte Ltd**AAD2006-083**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 214J

To Check Electrical Lighting Concerned.	\$	170.00	201
To rust-proofing of the affected areas.	\$	170.00	301
To check ABS and brake efficiency, final checking and testing.	\$	nn 380.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	170.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	201
To transfer of door fittings, attachment and perform water seepage test.	\$	nn 170.00	X
TOTAL	\$	14,930.00	
Over All Total	\$	35,769.35	

LUMP SUM (REPAIR DAY)~~20 DAYS~~

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: