

ASS. REC. BY:

REF:

LPL/2000 6866/K6

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PKQ 4218T

Yr Regn:

11, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Kia

Fortis

c.c

1591

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

64836

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KNAFX 411 MI = 5330532

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD / Rlm or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

30/6/20

D.O.I.

1/7/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8/7 L/Rng 8 40504 44000 Curfime

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS. SI

Firms

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

31/06/2020

Owner: LOW CHEE KOK

ESTIMATE TO REPAIR KIA FORTE K3 - SKQ4218T

1pc	rear boot cover	885
2pcs	rear boot cover hinge @\$69.50	
1pc	rear boot cover "KIA" logo	
1pc	rear boot cover "FORTE" emblem	
1pc	rear boot cover "K3" emblem	
1pc	rear boot cover "C&C" logo	
2pcs	rear boot cover side reflector @\$245.00	
1pc	rear boot cover inner lock	
1pc	rear boot cover inner rubber	
1pc	rear boot cover inner trim	
1pc	rear bumper	668
2pcs	rear bumper side retainer @\$35.00	
2pcs	rear bumper side reflector @\$95.00	
1pc	rear bumper diffused	347
1pc	rear bumper reinforcement	
2pcs	rear bumper reinforcement side bracket @\$55.00	
5pcs	rear bumper reinforcement top & lower bracket @\$25.00	
2pcs	rear taillamp @\$358.00	
2pcs	rear taillamp lower bracket @\$35.00	
1pc	rear end panel	
1pc	rear end panel inner garnish	
1pc	front bumper	
1pc	front bumper number garnish	
1pc	front bumper sponge	
1pc	front kia logo	
1pc	front centre grille	
	less 10%	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RM	\$	1,150.50	✓
R	\$	139.00	X
RM	\$	56.00	✓
RM	\$	52.00	✓
RM	\$	45.00	✓
RM	\$	55.00	✓
R	\$	490.00	X
RM	\$	158.00	✓
605N RM	\$	120.00	506N
R	\$	205.00	X
R	\$	898.50	✓
R	\$	70.00	X
old RM	\$	190.00	✓
RM	\$	355.20	✓
CM	\$	350.00	✓
R	\$	110.00	✓
\$RM	\$	125.00	X
old split	\$	716.00	✓
\$RM	\$	70.00	X
R	\$	480.00	✓
RM	\$	150.50	✓
R	\$	950.25	X
RM	\$	85.25	✓
R	\$	125.50	X
RM	\$	56.00	✓
R	\$	485.50	X
	\$	7,688.20	
	\$	768.82	
	\$	6,919.38	
short	\$	280.00	200N
RA RM	\$	100.00	405N
	\$	150.00	601
	\$	150.00	401
	\$	1,400.00	8001
Fee	\$	1,400.00	6501
	\$	8,999.38	

tuffkote
wiring
spray painting
Labour Charge
Total

