

Longpal
veh In.

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

31/06/2020

Owner: LOW CHEE KOK

ESTIMATE TO REPAIR KIA FORTE K3 - SKQ4218T

1pc	rear boot cover	\$	1,150.50
2pcs	rear boot cover hinge @\$69.50	\$	139.00
1pc	rear boot cover "KIA" logo	\$	56.00
1pc	rear boot cover "FORTE" emblem	\$	52.00
1pc	rear boot cover "K3" emblem	\$	45.00
1pc	rear boot cover "C&C" logo	\$	55.00
2pcs	rear boot cover side reflector @\$245.00	\$	490.00
1pc	rear boot cover inner lock	\$	158.00
1pc	rear boot cover inner rubber	\$	120.00
1pc	rear boot cover inner trim	\$	205.00
1pc	rear bumper	\$	898.50
2pcs	rear bumper side retainer @\$35.00	\$	70.00
2pcs	rear bumper side reflector @\$95.00	\$	190.00
1pc	rear bumper diffused	\$	355.20
1pc	rear bumper reinforcement	\$	350.00
2pcs	rear bumper reinforcement side bracket @\$55.00	\$	110.00
5pcs	rear bumper reinforcement top & lower bracket @\$25.00	\$	125.00
2pcs	rear taillamp @\$358.00	\$	716.00
2pcs	rear taillamp lower bracket @\$35.00	\$	70.00
1pc	rear end panel	\$	480.00
1pc	rear end panel inner garnish	\$	150.50
1pc	front bumper	\$	950.25
1pc	front bumper number garnish	\$	85.25
1pc	front bumper sponge	\$	125.50
1pc	front kia logo	\$	56.00
1pc	front centre grille	\$	485.50
	less 10%	\$	7,688.20
		\$	768.82
		\$	6,919.38
1set	rear parking sensor	s.nett \$	280.00
1set	front & rear number & casing	s.nett \$	100.00
	tuffkote	\$	150.00
	wiring	\$	150.00
	spray painting	\$	1,400.00
	Labour Charge	\$	1,400.00
	Total	\$	8,999.38

