

ASS. REC. BY:

REF:

A.G. / 20008867/Kd

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / XVS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S110 497J Yr Regn: OF, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude c.c. 1995Colour M. White / Red A/C: Insured / Std / NI / NASp. Reading 274742 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VI-1 ABL15/AUC 283466Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Sailun

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 8 mmL/Bal. 9 mm L/Bal. 8 mmD.O.A. 27/6/20 D.O.I. 30/6/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

/ Foot injury07402-38

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Fines _____

Others _____

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Not Authorized
Resuming B4 paint

Trans-cab Auto Services Pte Ltd

AAD2006-079

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 497J

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

30 JUN 2020

SHD 497J

VF1ABL15AUC283466

RENAULT

LATITUDE

27.6.2020

AI G

03-07-17

PART

- 1 BUMPER COVER REAR
- 1 BUMPER LOWER REAR
- 1 BUMPER BRACKET CTR REAR
- 1 BUMPER BRACKET SIDE RH REAR
- 1 BUMPER RETAINER RH REAR
- 1 BUMPER REFLECTOR RH
- 1 BUMPER BRACKET SIDE LH REAR
- 1 BUMPER RETAINER LH REAR
- 1 BUMPER REFLECTOR LH
- 1 BUMPER BEAM REAR
- 1 BUMPER BEAM BRACKET LH REAR
- 1 BUMPER BEAM BRACKET RH REAR
- 1 BUMPER BLOCK LH REAR
- 1 BUMPER BLOCK RH REAR
- 1 BUMPER HARNESS REAR
- 1 BOOT REAR
- 1 BOOT FINISHER
- 1 BOOT WHEATERSTRIP
- 1 BOOT REFLECTOR LAMP LH
- 1 BOOT REFLECTOR LAMP RH
- 1 BOOT BADGE 'RENAULT'
- 1 BOOT BADGE
- 1 BOOT STRUT LH
- 1 BOOT STRUT RH
- 1 BOOT HINGE LH
- 1 BOOT HINGE RH

LIST

\$	B ₁	561.70	✓
\$	C ₁	411.90	✓
\$	D ₁	98.10	✓
\$	D ₁	82.10	✓
\$	D ₁	59.80	✓
\$	C ₁	16.60	✓
\$	S ₁	80.80	X
\$	S ₁	54.20	X
\$	S ₁	16.60	X
\$	B ₁	547.80	✓
\$	R	114.50	X
\$	B ₁	100.90	✓
\$	S ₁	75.70	X
\$	S ₁	76.50	X
\$	S ₁	301.10	X
\$	B ₁	1,677.20	✓
\$	S ₁	344.70	X
\$	S ₁	178.20	X
\$	S ₁	277.70	X
\$	C ₁	277.70	✓
\$	R	82.40	✓
\$	R	95.80	✓
\$	S ₁	145.10	X
\$	J ₁	145.10	X
\$	R	254.20	X
\$	R	253.80	X

Trans-cab Auto Services Pte Ltd

AAD2006-079

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 497J

1	BOOT TRIM BOARD	\$	Sn	611.00	
1	BOOT LOCK	\$	R	246.60	
1	BOOT LOCK CATCH	\$	R	41.70	
2	BOOT RUBBER PLUG	\$	Sn	139.30	}
1	BOOT SWITCH	\$	Sn	113.00	
1	BOOT LOCK LINKAGE HOLDER	\$	Sn	99.50	
2	LICENCE PLATE LAMP	\$	Sn	26.30	
1	TAILLAMP RH	\$	mg CM	401.40	✓
1	TAILLAMP PANEL RH	\$	R	401.40	X
1	TAILLAMP LH	\$	Sn	401.40	X
1	TAILLAMP PANEL LH	\$	R	401.40	X
1	OUTER PANEL REAR (End Panel)	\$	Ry	745.80	✓
1	OUTER PANEL REAR (End Panel) TRIM	\$	Dir	404.56	✓
1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	1,229.40	}
1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	
1	SPARE WHEEL PANEL BRACKET LH L70Y	\$	R	70.60	
1	SPARE WHEEL PANEL BRACKET RH L70Y	\$	R	69.20	
1	SPARE TYRE BOARD	\$	Sn	680.90	
1	EXHAUST REAR	\$	R	5,263.60	
1	EXHAUST CAP REAR	\$	R	125.40	
1	FENDER PANEL REAR RH	\$	R	1,933.20	}
1	FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	
1	WHEELARCH REAR RH	\$	Sn	275.40	
TOTAL		\$		21,294.92	
10%		\$		2,129.49	
		\$		19,165.43	

Special Nett

1SET PARKING AID	\$	Shon	700.00	Goosm
1SET REAR BUMPER CLIP	\$	na	75.00	—
1SET BUMPER BRACKET CTR CLIP	\$	na	40.00	X
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	40.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	na	45.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	40.00	X

Trans-cab Auto Services Pte Ltd**AAD2006-079**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 497J

1SET BUMPER RETAINER CLIP LH RR	\$	na	45.00	X
1SET BUMPER LOWER REAR RIVET	\$	na	55.00	X
1SET BUMPER LOWER REAR CLIP	\$	na	75.00	✓
1 FENDER INNER TRIM CLIP RH	\$	na	45.00	X
1SET FENDER WHEELARCH REAR RH CLIP	\$	na	45.00	X
2 END PANEL SEAM SEALANT	\$	na	170.00	X
1SET BOOT FINISHER CLIP	\$	na	40.00	X
1 BOOT STICKER "Trans-cab"	\$	na	80.00	30% —
1 EXHAUST MOUNTING REAR	\$	sh	40.00	X
1 EXHAUST BRACKET REAR	\$	sh	40.00	X
1 BOOT STICKER "6555-3333"	\$	na	80.00	30% —
1 BOOT TRIM BOARD CLIP	\$	na	45.00	X
1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sh	385.00	X
1 SPARE TYRE	\$	sh	330.00	X
1 TAILLAMP CLIP RH	\$	na	35.00	5.00
2 REAR WINDSCREEN SEALANT	\$	na	150.00	} X
1 WINDSCREEN MOULDING	\$	na	190.00	
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	120.00	
1 TAILLAMP CLIP LH	\$	na	35.00	
1 Rear Bumper Protector	\$	na	150.00	
1SET Rear licence plate with holder	\$	sh	120.00	
1SET END PANEL INSULATION PAD	\$	sh	200.00	
1SET REAR END PANEL TRIM CLIP	\$	na	40.00	
TOTAL	\$		3,455.00	
TOTAL PARTS	\$		22,620.43	

LABOUR

To remove and refit rear windscreen glass to facilitate bodywork repair.	\$	na	170.00	X
To repair and realign rear exhaust pipe.	\$	na	170.00	X
To Rust-Proofing Of The Affected Areas.	\$		170.00	60%

Trans-cab Auto Services Pte Ltd**AAD2006-079**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 497J

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>7001</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00	<i>X</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>7</i> 380.00	<i>X</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>7</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	380.00	<i>601</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	<i>8801</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>7</i> 170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>7</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>7</i> 220.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>7</i> 380.00	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD2006-079**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 497J

To Check Electrical Lighting Concerned.	\$	170.00	20%
To reinstall rear bumper parking sensor.	\$	170.00	60%
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	na 170.00	X
TOTAL	\$	15,820.00	
Over All Total	\$	38,440.43	

(PART BY PART) Repair Days**25 DAYS****5 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD497J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Jun 2020
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	M9R8839C003273
Chassis No.:	VF1ABL15AUC283466
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	03 Jul 2017
First Registration Date:	03 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Jul 2025
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	02 Jul 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$38,560.00
COE Rebate Amount:	\$24,139.00
Total Rebate Amount:	\$39,137.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 29 Jun 2020

OK