

Not Authoised
Resumy B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 497J

AAD2006-079

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

30 JUN 2020

SHD 497J

VF1ABL15AUC283466

RENAULT

LATITUDE

27.6.2020

AIK

03-07-17

PART

LIST

1	BUMPER COVER REAR	\$	B ₁	561.70	✓
1	BUMPER LOWER REAR	\$	C ₁	411.90	✓
1	BUMPER BRACKET CTR REAR	\$	D ₁	98.10	✓
1	BUMPER BRACKET SIDE RH REAR	\$	D ₁	82.10	✓
1	BUMPER RETAINER RH REAR	\$	D ₁	59.80	✓
1	BUMPER REFLECTOR RH	\$	C ₁	16.60	✓
1	BUMPER BRACKET SIDE LH REAR	\$	S ₁	80.80	X
1	BUMPER RETAINER LH REAR	\$	S ₁	54.20	X
1	BUMPER REFLECTOR LH	\$	S ₁	16.60	X
1	BUMPER BEAM REAR	\$	B ₁	547.80	✓
1	BUMPER BEAM BRACKET LH REAR	\$	R	114.50	X
1	BUMPER BEAM BRACKET RH REAR	\$	B ₁	100.90	✓
1	BUMPER BLOCK LH REAR	\$	S ₁	75.70	X
1	BUMPER BLOCK RH REAR	\$	S ₁	76.50	X
1	BUMPER HARNESS REAR	\$	S ₁	301.10	X
1	BOOT REAR	\$	B ₁	1,677.20	✓
1	BOOT FINISHER	\$	S ₁	344.70	X
1	BOOT WHEATERSTRIP	\$	S ₁	178.20	X
1	BOOT REFLECTOR LAMP LH	\$	S ₁	277.70	X
1	BOOT REFLECTOR LAMP RH	\$	C ₁	277.70	✓
1	BOOT BADGE 'RENAULT'	\$	R	82.40	✓
1	BOOT BADGE	\$	R	95.80	✓
1	BOOT STRUT LH	\$	S ₁	145.10	X
1	BOOT STRUT RH	\$	S ₁	145.10	X
1	BOOT HINGE LH	\$	R	254.20	X
1	BOOT HINGE RH	\$	R	253.80	X

Trans-cab Auto Services Pte Ltd

AAD2006-079

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 497J

1	BOOT TRIM BOARD	\$	Sn	611.00	
1	BOOT LOCK	\$	R	246.60	
1	BOOT LOCK CATCH	\$	R	41.70	
2	BOOT RUBBER PLUG	\$	Sn	139.30	}
1	BOOT SWITCH	\$	Sn	113.00	
1	BOOT LOCK LINKAGE HOLDER	\$	Sn	99.50	
2	LICENCE PLATE LAMP	\$	Sn	26.30	
1	TAILLAMP RH	\$	mg CM	401.40	✓
1	TAILLAMP PANEL RH	\$	R	401.40	X
1	TAILLAMP LH	\$	Sn	401.40	X
1	TAILLAMP PANEL LH	\$	R	401.40	X
1	OUTER PANEL REAR (End Panel)	\$	R	745.80	✓
1	OUTER PANEL REAR (End Panel) TRIM	\$	Dis	404.56	✓
1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	1,229.40	}
1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	
1	SPARE WHEEL PANEL BRACKET LH L70Y	\$	R	70.60	
1	SPARE WHEEL PANEL BRACKET RH L70Y	\$	R	69.20	
1	SPARE TYRE BOARD	\$	Sn	680.90	
1	EXHAUST REAR	\$	R	5,263.60	
1	EXHAUST CAP REAR	\$	R	125.40	
1	FENDER PANEL REAR RH	\$	R	1,933.20	
1	FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	}
1	WHEELARCH REAR RH	\$	Sn	275.40	
TOTAL		\$		21,294.92	
10%		\$		2,129.49	
TOTAL PAID		\$		19,165.43	

Special Nett

1SET PARKING AID	\$	Short	700.00	600.00
1SET REAR BUMPER CLIP	\$	na	75.00	—
1SET BUMPER BRACKET CTR CLIP	\$	na	40.00	X
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	40.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	na	45.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	40.00	X

Trans-cab Auto Services Pte Ltd

AAD2006-079

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 497J

1SET BUMPER RETAINER CLIP LH RR	\$	na	45.00	X
1SET BUMPER LOWER REAR RIVET	\$	na	55.00	X
1SET BUMPER LOWER REAR CLIP	\$	na	75.00	✓
1 FENDER INNER TRIM CLIP RH	\$	na	45.00	X
1SET FENDER WHEELARCH REAR RH CLIP	\$	na	45.00	X
2 END PANEL SEAM SEALANT	\$	na	170.00	X
1SET BOOT FINISHER CLIP	\$	na	40.00	X
1 BOOT STICKER "Trans-cab"	\$	na	80.00	30% —
1 EXHAUST MOUNTING REAR	\$	sh	40.00	X
1 EXHAUST BRACKET REAR	\$	sh	40.00	X
1 BOOT STICKER "6555-3333"	\$	na	80.00	30% —
1 BOOT TRIM BOARD CLIP	\$	na	45.00	X
1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sh	385.00	X
1 SPARE TYRE	\$	sh	330.00	X
1 TAILLAMP CLIP RH	\$	na	35.00	5.00 —
2 REAR WINDSCREEN SEALANT	\$	na	150.00	} X
1 WINDSCREEN MOULDING	\$	na	190.00	
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	120.00	
1 TAILLAMP CLIP LH	\$	na	35.00	
1 Rear Bumper Protector	\$	na	150.00	
1SET Rear licence plate with holder	\$	sh	120.00	
1SET END PANEL INSULATION PAD	\$	sh	200.00	
1SET REAR END PANEL TRIM CLIP	\$	na	40.00	
TOTAL	\$		3,455.00	

TOTAL PARTS \$ 22,620.43**LABOUR**

To remove and refit rear windscreen glass to facilitate bodywork repair.

\$ na 170.00 X

To repair and realign rear exhaust pipe.

\$ na 170.00 X

To Rust-Proofing Of The Affected Areas.

\$ 170.00 60%

Trans-cab Auto Services Pte Ltd

AAD2006-079

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 497J

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>7000</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>7</i> 380.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>7</i> 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	380.00	<i>600</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	<i>8800</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>7</i> 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>7</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>7</i> 220.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>7</i> 380.00	X

Trans-cab Auto Services Pte Ltd

AAD2006-079

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 497J

To Check Electrical Lighting Concerned.	\$	170.00	201
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	na 170.00	X
TOTAL	\$	15,820.00	
Over All Total	\$	38,440.43	

(PART BY PART) Repair Days

25 DAYS

5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: