

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 8608 0808

Email: auburnauto.claim@gmail.com

Vehicle No: SMJ4434Z

Model: TOYOTA WISH

QTY	Description	Repairer's Estimate
Spare Parts - List Items		
1	Rear Tailgate / DD	\$ 1,200.00 /
1	Rear Taillamp Tailgate trim board ? / BR	\$ 800.00 605-10 /
1	Rear Tailgate Lamp (LH) ? / BR	\$ 600.00 548-99 /
1	Rear Tailgate Mechanism X NN	\$ 400.00 X
1	Rear Tailgate Lock / BT	\$ 280.00 /
1	Rear Bumper / DD	\$ 1,500.00 566 /
1	Rear Bumper Side Retainers / BR	\$ 170.00 149 /
1	Bumper Sensor X NN	\$ 120.00 X
1	Rear Bumper Reflectors (LH) ? / BR	\$ 380.00 50
1	Rear Bumper Top Step Garnish Tailgate moulding \$ / TN	\$ 150.00 /
1	Rear End Panel ? / DD	\$ 480.00 /
1	Rear End Panel Inner Garnish ? / BR	\$ 120.00 /
1	Rear Boot Garnish X NN	\$ 100.00 X
1	Hydraulic Hinge Tailgate garnish chrome ? / BR	\$ 200.00 /
2	Rubber Moulding X NN	\$ 40.00 X
1	Number Plate X NN	\$ 120.00 X
1	Rear Reverse Camera Windscreen moulding / nec	\$ 180.00 /
1	Rear Tailgate "Toyota" Emblem / nec	\$ 160.00 66-15 /
1	Rear Tailgate "WISH" Emblem / nec	\$ 120.00 62-70 /
	Valve mod/c	

4648-35
- 25%
3486-26

\$ 7,120.00

c/f: \$

\$ 7,120.00

Special Nett Items		AMT SS
1	Rear Windscreen Sealant ✓ <i>MC</i>	\$ 120.00 <i>40</i>
1	Back bumper clip ✓ <i>MC</i>	\$ 150.00 <i>30</i>
1	Rear Reverse Sensor (1 set) ✓ <i>SL</i>	\$ 620.00 <i>200</i>
		<u>\$ 890.00</u> <i>270</i>

S/N. Labour Charges

Remove and refit rear tailgate	\$ 300.00 <i>200</i>
Remove and refit rear bumper	\$ 300.00 <i>200</i>
Remove and Refit Rear Panel	\$ 800.00 <i>400</i>
Remove, refit and replaced damage lamps and check up rear electrical wiring	\$ 150.00 <i>30</i>
Remove and refit inner garnishes trim to assist repair	\$ 200.00 <i>30</i>
Remove and refit rear reverse sensor	\$ 240.00 <i>30</i>
To apply undercoating on replaced panel	\$ 120.00 <i>30</i>
To Respray Painting.	\$ 1,000.00 <i>600</i>

\$	<u>3,110.00</u>	<i>1520</i>
----	-----------------	-------------

GRAND TOTAL

P-3486-26
M- 270
L- 1520
5276-26

\$	<u>11,120.00</u>
----	------------------

L/S- 4221-00
= 4200
Page 2 of 3

Survey:

1st / 2nd / 3rd

(delete accordingly)

Surveyor Details:

(Name)

Steve (LKK)

(Contact)

(Email)

(Signature)

(Date/Time)

WHL Phil

L/S

AL SM

5/6 days

2/7/20, 2:00 pm

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: