

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

WIP NO. 39468

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0453/2020/NS
Date : 29-Jun-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

4 dzyx - ok - jb 24 Oct 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Raymond's Maths And Science Studio
Address : Blk 280 Bishan St 24
#01-22
Singapore 570280
Telephone : HP +65 98331850
Type of Claim : Third Party Claims
Policy No. : 2100431672-04
Vehicle No : **SKV 7776 C**
Model Code : Audi Q3 1.4 TFSI S TRONIC
Model / Year : 30-Sep-15
Engine No : CZD 215462
Chassis No : WAUZZZ8U4GR027598
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Jun-20
Place of Accident : Temasek Blvd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKV 7776 C

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	
2	To remove and transfer lhs front door's multi-lock system and power window devices. Inspect for damages.	S/N \$	280.00	\$ 280.00
3	To dismantle and renew front bumper, lhs front fender and lhs front door. Re-organise crash management components. Reinstall all parts removed.	\$	3,200.00	\$ 1,000.00
4	To respray front bumper, lhs front fender, lhs front door, both front wheel arch rims and door cover. (Added \$200.00 door cover)	\$	4,500.00	\$ 1,700.00
5	To renew lhs front rim. To carry out wheel alignment.	S/N \$	280.00	\$ 280.00
6	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 7776 C

S/N	Parts Description	Damaged Parts & Prices		
			S/Nett	Remarks
1	FRONT BUMPER		\$ 1,846.00	
2	FRONT BUMPER FIXING PARTS		\$ 103.00	
3	HEADLIGHT MOUNTING - LH		\$ 112.00	
4	FRONT FENDER - LH		\$ 850.00	
5	FRONT FENDER ATTACHMENT PARTS		\$ 66.00	
6	FRONT FENDER BRACKET - LH		\$ 78.00	
7	FRONT FENDER BRACE - LH FRONT		\$ 98.00	
8	WHEEL HOUSING LINER - LH		\$ 226.00	
9	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 145.00	
10	FRONT WHEEL SPOILER - LH		\$ 69.00	
11	FRONT WHEEL COVER - LH / RH	2	\$ 994.00	\$ 795.20
12	FRONT DOOR - LH		\$ 2,512.00	\$ 2,009.60
13	FRONT DOOR OUTER SEAL - LH	NEC	\$ 156.00	\$ 124.80
14	PROTECTIVE FILM		\$ 25.00	\$ 19.28
15	FRONT DOOR ATTACHMENT PARTS		\$ 101.00	
16	BONDING AGENT	NEC	\$ 46.00	
17	CLEANING SOLUTION	NEC	\$ 64.00	
18	FRONT DOOR CATCH		\$ 113.00	
19	FRONT DOOR COVER - LH		\$ 420.00	\$ 336.00
20	FRONT ALUMINIUM RIM - LH		TBC	
21	SUNDRIES		\$ 400.00	\$ 667.20
TOTAL SPARE PARTS CHARGES		:	\$ 8,424.00	\$ 3,952.08
TOTAL LABOUR CHARGES		:	\$ 8,812.00	\$ 3,452.00
GRAND TOTAL		:	\$ 17,236.00	\$ 7,404.08

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

BL-05/08/20

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant