



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20006882/Utf3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 17-09-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKE 3468H	Veh. Inspected	YL 5160D
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2001616/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	01/07/2020

2. Vehicle Particulars & Condition

Make & Model	HINO XZU605R (M)	c.c	4009
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JHHACS3H10K002902	Colour	WHITE
Odometer	110083	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/85 R16	YOKOHAMA	6 mm
L/H Front Tyre	195/85 R16	YOKOHAMA	6 mm
R/H Rear Tyre	195/85 R16 (D)	YOKOHAMA	6/6 mm
L/H Rear Tyre	195/85 R16 (D)	YOKOHAMA	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/05/2020	Inspection Date	03/07/2020
Survey held at	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
--	-----------------------