

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 39773

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0461/2020/NS  
**Date** : 1-Jul-20

**Vehicle NOT IN workshop. Kindly arrange for survey.**

**Your insured veh no : YP 607 U**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Chinniah Ilango  
**Address** : Blk 440B Bukit Batok West Ave 8  
#13-725  
Singapore 652440  
**Telephone** : (HP) +65 88553131  
**Type of Claim** : Third Party Claims  
**Policy No.** : 1800134782-01  
**Vehicle No** : **SMG 3131 U**  
**Model Code** : Audi A3 Sedan 1.4 TFSI CO  
**Model / Year** : 13/11/2018  
**Engine No** : CZE 846360  
**Chassis No** : WAUZZZ8V2K1003641  
**Mileage** : -  
**Date In** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 30-Jun-20  
**Place of Accident** : Sarimbun Recycling Park

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SMG 3131 U

S/n	Nature of Jobs	Estimated Charges	Survivor's Recommendations
1	To remove and transfer rhs headlight control units and power modules. To carry out calibration.	S/N \$ 350.00	X
2	To dismantle and renew front bumper and bonnet. Re-organise crash management components. Reinstall all parts removed.	\$ <del>2,100.00</del>	1000
3	To respray front bumper, bonnet and hinges.	\$ <del>2,500.00</del>	1100
4	To carry out diagnostic check.	S/N \$ 192.00	
<b>TOTAL LABOUR CHARGES</b>		<b>: <u>\$ 5,142.00</u></b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMG 3131 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Pop</i>	\$ 1,894.00	+
2	FRONT BUMPER FIXING PARTS <i>Green</i>	\$ 176.00	+
3	FRONT BUMPER GRILLE - CENTRE	\$ 151.00	+
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE?	\$ 505.00	+
5	FRONT BUMPER CLOSING ELEMENT - LH / RH	\$ 560.00	+
6	FRONT BUMPER COVER TRIM - LH / RH	\$ 306.00	+
7	RADIATOR GRILLE <i>ct</i>	\$ 1,338.00	✓
8	RADIATOR GRILLE CLOSING ELEMENT ?	\$ 180.00	?
9	AIRCON STICKER <i>NEC</i>	NEC \$ 7.00	✓
10	CAUTION SIGN STICKER	NEC \$ 13.00	✓
11	FRONT BUMPER SIDE REINFORCEMENT BEAM?	\$ 681.00	+
12	FRONT BUMPER FOAM FILLER PIECE <i>Free</i>	\$ 178.00	+
13	FOAM FILLER PIECE COVER	\$ 115.00	+
14	BONNET <i>Dented</i>	\$ 2,988.00	✓
15	BONNET ATTACHMENT PARTS ?	\$ 155.00	?
16	BONNET LID HINGE - LH / RH	2 \$ 116.00	+
17	BONNET CATCH HOOK <i>Free</i>	\$ 84.00	+
18	BONNET STRIKER - RH	\$ 104.00	+
19	BONNET EDGE PROTECTION ?	\$ 26.00	?
20	BONNET LID LOCK <i>Free</i>	\$ 202.00	+
<b>SUB TOTAL SPARE PARTS</b>		<b>: \$ 9,779.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel. 6366 2323 Fax 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMG 3131 U

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
21	BONNET BOWDFEN CABLE - CENTRE	\$	54.00	X
22	BONNET CATCH HOOK	\$	60.00	X
23	LED HEADLIGHT - RH	\$	5,193.00	X
24	LIFT CYLINDER - RH	\$	134.00	X
25	RADIATOR AIR GUIDE - UPPER CENTRE	\$	12.00	X
26	TEMPERATURE SENSOR BRACKET	\$	18.00	X
27	RADIATOR AIR GUIDE - LH / RH	2 \$	46.00	X
28	FRONT NO PLATE <i>me</i>	S/N \$	60.00	✓
29	SUNDRIES ?	\$	300.00	?
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 15,656.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 5,142.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 20,798.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** : Adrian L  
**Surveyed Date** : 03/07/20  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** : Not Authorised, 04 Days.

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant