

ASS. REC. BY:

REF:

TU / 20006891/Kg

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLG 9300C

Yr Regn:

01, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes

3

c.c

1998

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

58827

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN6BM 4278G 0323559

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

225/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

26/6/20

D.O.I.

1/7/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/7 11/2 8445a Carfax

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

LIM GUEK LAN

King's Auto Spray Paint Pte Ltd
 B1K 160 Sin Ming Drive #05-10
 Sin Ming Authority Singapore 575722

Not Notchish
 Resurvey After Paint
 30-6-20
 11amp @ 450p
 Maza 3

Re: Estimate cost for SCG 9300C

SUPPLY OF PARTS:

- ipc front bumper top
- ipc front bumper
- ipc front bumper lower grille center
- ipc front bumper towing cover
- ipc front bumper nozzle
- ipc front bumper nozzle cover
- 2pc front bumper brackets @ 25.00
- 2pc front bumper retainer side @ 20.70
- ipc front bumper beam
- ipc front bumper beam outer garish
- ipc front bumper sponge
- 1pc front bumper top panel
- ipc front top panel garish
- 6pc front top panel garish clips @ 3.50
- ipc front sport lamp
- ipc front sport lamp cover
- ipc front sport lamp midg
- ipc front sport lamp chromel
- ipc front grille center
- 2pc front grille midg @ 186.70
- ipc front grille logo
- ipc front Head lamp
- ipc front grille inner panel
- ipc front bonnet lock

Bu	\$ 335.10	✓
Bu	1031.70	✓
sn	153.00	x
sn	28.60	x
sn	242.40	x
sn	85.40	x
diy	50.00	✓
sn	41.40	x
sn	665.10	✓
cm	258.40	✓
sn	150.40	✓
sn	320.60	x
sn	335.10	x
sn	21.00	x
sn	351.40	✓
sn	46.40	✓
sn	106.70	x
sn	80.00	x
cm	681.60	✓
cl/crm	373.40	✓
sn	44.20	✓
my cm	2245.00	✓
sn	55.00	✓
sn	330.00	x
	8031.90	
	1606.38	
	6425.52	
sn	40.00	25ja
	40.00	20c
	800.00	500c
	800.00	650c
	8105.52	

LABOUR:

- ipc front number plates
- check wiring

To renew the above mentioned parts
 knocking, cutting, welding & straighten
 front damaged parts

spray paintings

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental Work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: *SCR*
 Date: