

LIM GUER LAN

King's Auto Spray Paint Pte Ltd
 BIK 166 Sin Ming Drive #05-10
 sin ming Autocare Singapore 575722

Not Notified
 Resurvey After Paint
 30-6-20 4 DAYS

Re: Estimate cost for SCG 9300 C MAZDA 3

SUPPLY OF PARTS:

1pc front bumper top	Bu \$ 335.10 —
1pc front bumper	Bu 1031.70 —
1pc front bumper lower grille center	sn 153.00 x
1pc front bumper towing cover	sn 28.60 x
1pc front bumper nozzle	sn 242.40 x
1pc front bumper nozzle cover	sn 85.40 x
2pc front bumper brackets @ 25.00	diy 50.00 2
2pc front bumper retainer side @ 20.70	sn 41.40 x
1pc front bumper beam	sn 665.10 2
1pc front bumper beam outer garish	cm 258.40 2
1pc front bumper sponge	sn 150.40 x
1pc front bumper top panel	sn 320.60 x
1pc front top panel garish	sn 335.10 x
6pc front top panel garish clips @ 3.50	sn 21.00 x
1pc front sport lamp	sn 351.40 x
1pc front sport lamp cover	sn 46.40 x
1pc front sport lamp midg	sn 106.70 x
1pc front sport lamp chromed	sn 80.00 x
1pc front grille center	cm 681.60 —
2pc front grille midg	cm 373.40 4
1pc front grille logo	sn 44.20 —
1pc front head lamp	my car 2245.00 2
1pc front grille inner panel	sn 55.00 x
1pc front bonnet lock	sn 330.00 x

LABOUR:

1pc front number plates
 check wiring

To renew the above mentioned parts
 knocking, cutting, welding & straighten
 front damaged parts

Spray Paintings

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: *SCR*
 Date:

\$ 8031.90	
1666.38	
6425.52	
40.00	25A
40.00	20C
\$ 800.00	500L
\$ 800.00	650L
\$ 8105.52	