

ASS. REC. BY:

REF:

AIG / 200088P2 / Kd

C

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ Yec Arw

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 01 days Res.: Yes or NoLum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SM E 8001 P Yr Regn: 10, 18Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prv C.C. 1798Colour: M.D. Blue A/C: Insured / Std / NI / NASp. Reading: 43308 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTD ES 3 EU 00 J 03895Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rlm / STD / A/Rlm or

Tyre Size: F: _____

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 29/6/20 D.O.I. 1/7/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Acc o/s

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

24/7 @ 220h Ca. frame

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Survey Fee:

Transportation:

S + RS: \$

Fees:

Others:

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
 Email: yeeautopte ltd@gmail.com
 Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16
 Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 29/06/2020
 TP Veh Reg No: SGU3177K

Estimate No: ES2000056
 Date: 01 Jul 2020
 Policy No:
 Veh Reg No: SME8001P
 Make/Model: TOYOTA PRIUS PLUS (AUTO)
 Chassis No: JTDZS3EU00J033895
 Engine No: 2ZR0C55443
 Reg. Date: 18/10/2018

Estimate Repair Cost to Vehicle No :SME8001P

Description	U/Price	Quantity	List Price SS	Amount SS
Spare Parts				
1 REAR BUMPER	895.20	1 PC	895.20 X	
2 REAR BUMPER SIDE RETAINER - LH	65.20	1 PC	65.20 X	
3 REAR BUMPER SIDE RETAINER - RH	65.20	1 PC	65.20 X	
4 TAIL LAMP RH	585.50	1 PC	585.50 X	
5 REAR BUMPER REFLECTOR - RH	185.00	1 PC	185.00 X	
6 REAR BUMPER SPOILER	350.00	1 PC	350.00 X	
			2,146.10	2,146.10
Labour				
7 TO DISMANTLE & REPLACE DAMAGED PARTS. PANEL BEAT WHERE NECESSARY.	800.00	1 JOB	800.00 X	
8 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	800.00	1 JOB	800.00 22d	
9 TO CHECK WIRING FUNCTIONS.	50.00	1 JOB	50.00 X	
			1,650.00	1,650.00
Total				SS 3,796.10
Add GST @ 7%				265.73
Total Amount Payable				SS 4,061.83

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND SIXTY ONE AND CENTS EIGHTY THREE ONLY

Not Withheld

1 day

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: