



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 29/06/2020
TP Veh Reg No: SGU3177K

Estimate No: ES2000056
Date: 01 Jul 2020
Policy No:
Veh Reg No: SME8001P
Make/Model: TOYOTA PRIUS PLUS (AUTO)
Chassis No: JTDZS3EU00J033895
Engine No: 2ZR0C55443
Reg. Date: 18/10/2018

Estimate Repair Cost to Vehicle No :SME8001P

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Spare Parts				
1 REAR BUMPER	895.20	1 PC	895.20 X	
2 REAR BUMPER SIDE RETAINER - LH	65.20	1 PC	65.20 X	
3 REAR BUMPER SIDE RETAINER - RH	65.20	1 PC	65.20 X	
4 TAIL LAMP RH	585.50	1 PC	585.50 X	
5 REAR BUMPER REFLECTOR - RH	185.00	1 PC	185.00 X	
6 REAR BUMPER SPOILER	350.00	1 PC	350.00 X	
			2,146.10	2,146.10
Labour				
7 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	800.00	1 JOB	800.00 X	
8 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	800.00	1 JOB	800.00 220	
9 TO CHECK WIRING FUNCTIONS.	50.00	1 JOB	50.00 X	
			1,650.00	1,650.00
Total				S\$ 3,796.10
Add GST @ 7%				265.73
Total Amount Payable				S\$ 4,061.83

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND SIXTY ONE AND CENTS EIGHTY THREE ONLY

Not Withdraw

1 day

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: