

JMFORTDELLGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO : SHAGUZX
MAKE : HYUNDAI
MODEL : I40

DATE: 30. Jun. 2020

DOA: 30. Jun. 2020

NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover			\$1,052.20
1	Front Bumper Side Bracket - RH			\$24.60
1	Front Bumper Top Bracket - RH			\$22.40
10	Front Bumper Clips		\$2.20	\$22.00
1	Headlamp Support Panel			\$907.40
1	Front Fender - RH			\$663.00
1	Front Fender Shield - RH			\$174.90
1	Headlamp - RH			\$1,388.00
1	Front Wheel Cover - RH			\$107.10
1	Side Mirror - RH			\$670.00
SUB TOTAL			1866.70	\$5,031.60
LESS 20%			1455.48	\$1,006.32
DISCOUNTED TOTAL				\$4,025.28
1	Advertisement - RHF Fender		100	\$100.00
				\$100.00
				\$600.00
				\$500.00
				\$80.00
				\$80.00
TOTAL LABOUR			1020	\$1,260.00
ESTIMATE TOTAL			2575.48	\$5,385.28

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to the approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Labour Charge

- 1 Panel Beating
- 1 Spray Painting Charge
- 1 Tuff Kote
- 1 Wiring Charge

Tan Jia 97495719
1/7/20 @ 11am
bump sum
Resurvey after repair
03 days
Tan Jia @ 11am

Larry Ng

4/2100
3 days

de ✓
Xnn
de ✓
de ✓
Xnn
de ✓
Xnn
Xnn
de ✓
Xnn

Nett

560
400
30
30