

SJQ 7824K.
Suzuki Swift
JSAE2C31500204332

TPAIG,
Asher

Front Number Plate Canceled	30(SN) ✓
Front Bumper Distorted	518.70 ✓
Front Bumper Clips. New	30 ✓
Front Bumper Side Holder x02 New	$29.2 \times 2 = 58.40$ ✓
Front Bumper Reinforcement Upper Best	143.70 ✓
Front Bumper Reinforcement Cover Upper Canceled	76.70 ✓
Front Bumper Reinforcement Lower New	125.70 ✗
Front Bumper Reinforcement Cover Lower Canceled	76.70 ✓
Front Bumper Fog Lamp x 02 Canceled	$219.2 \times 2 = 438.40$ ✓
Front Bumper Fog Lamp Cover x 02 Included	$259.3 \times 2 = 518.60$ ^{259.30}
Front Bumper Fog Lamp Cover Garnish x 02 New	$45.1 \times 2 = 90.20$ ✗
Front Bumper Lower Wire Mesh New	150(SN) ✗
Front Bumper Lower Spoiler Deformed	1200(SN) 750(SN)
Front Bumper Tow Cover New	24.30 ✓
Front Grille Canceled	350(SN) 280(SN)
Front Grille Clips. New	20 ✓
Headlamp x 02 Canceled.	$485.3 \times 2 = 970.60$ ✓
Oil Cooler Dented	500(SN) 380(SN)
Oil Cooler Lower Aluminium Sheet x 02 Best	$150 \times 2 = 300$ (SN) 120(SN)
Air Con Condenser Dented	471.70 ✓
Radiator New	632.40 ✗
Front Support Panel. Repair	551.50 ✗
Front Fender x 02 Repair	$471 \times 2 = 942$ ✗
Rear Number Plate Canceled	30(SN) ✓
Rear Number Plate Lamp x 02 Canceled	$41.8 \times 2 = 83.60$ ✓
Rear Bumper Distorted	605 ✓
Rear Bumper Clips. New	30 ✓
Rear Bumper Side Holder x 02 New	$35.1 \times 2 = 70.20$ ✓

ABC

SJQ7824K

Rear Bumper Wire Mesh x 02	N-P m	65 x 2 = 130(SN) X
Rear Bumper Lower Spoiler	Delivered	1200(SN) 600(SN)
Rear Bumper Lamp x 02	included	121 x 2 = 242 ✓
Rear Bumper Impact Bracket x 02	RH Dented	47.2 x 2 = 94.40 47.20
Reverse Sensor	Delivered	250(SN) 700(SN)
Rear Camera	Delivered	500(SN) 400(SN)
Rear End Panel	Dented	395.60 ✓
Rear End Panel Top Garnish	included	7340 ✓
Rear End Panel Top Garnish Clips	del	20 ✓
Rear End Panel Air Vent	N-P m	36 X
Rear End Panel Sealant	del	60(SN) ✓
Taillamp x 02	included	289.7 x 2 = 579.40 ✓
Taillamp Panel x 02	Paper	114.5 x 2 = 229 X
Tailgate	Dented	680.20 ✓
Tailgate Lock	Delivered	149.50 ✓
Tailgate Weatherstripe	del	76.60 ✓
Tailgate Outer Handle Switch	Delivered	78.60 ✓
Tailgate Inner Trim Board	included	172.20 ✓
Tailgate Inner Trim Board Clips	del	30 ✓
Tailgate Glass Moulding	del	100.20 ✓
Tailgate Glass Sealant	del	60(SN) ✓
Tailgate Stickers	del	280(SN) 100(SN)
Rear Fender Inner Trim Board x 02	N-P m	110.6 x 2 = 221.20 X
Rear Fender Inner Trim Board Clips	N-P m	60 X
Spere Tyre Panel	Paper	589.50 X
Spere Tyre Panel Top Cover	N-P m	714.5 X
Spere Tyre Panel Insulation Pad	del	250(SN) 200(SN)
Rear Exhaust Pipe	N-P m	579.30 X
Rear Exhaust Mounting x 02	N-P m	28 x 2 = 56 X
Spere Tyre Panel Foldable Board	included	268 ✓

ABC

SJA7824K

Panel Beating	2200	1600
Spray Painting	2200	1800
Wiring	150	100
To remove upholstery and rear seat	350	120
To remove reverse sensor	100	50
To remove rear camera	100	50
To remove rear video recorder	100	50
To remove exhaust pipe	150	80
To transfer tailgate fittings and tailgate spoiler	250	120
To remove tailgate glass	150	120
To remove condenser and radiator and to top up aircon gas.	180	120

hist: 6760.50
 tax 15%: 5746.42
 SN: 3310

labour: 4210
 total: 13166.42
 A/S: 10 SK
 12 Days

10.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

ABC