

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd  
20 McCallum Street  
#09-01 Tokio Marine Centre  
Singapore 069046From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Ng Kwai Kay Francis

Date: 03 Jul 2020

**Preliminary Advice**

Insured Vehicle No	:	SGL1494E		
TP Vehicle No	:	SHD4236U	Accident Date	: 01/07/2020
Make	:	HYUNDAI IONIQ HYBRID	Assignment Date	: 02/07/2020
Date of Inspection	:	02/07/2020	Est. Duration of Repair	: 3
Inspection At	:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969		

**Point of Impact / General Description of Damages**

The vehicle sustained damages at the n/s portion.

Repairer's Estimate (Gross)	:	S\$ 6,080.32
Revised Amount	:	S\$ 1,943.12
Check Items (Estimated)	:	S\$ 0.00
Total	:	S\$ 1,943.12
Lump Sum Repair		:

**Total Loss Consideration**

New for Old Value	:	S\$
Pre-Accident Value	:	S\$
COE / PARF Rebate	:	S\$
Salvage Value	:	S\$
Margin for Repair	:	S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :