

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jul 2020		02 Jul 2020 12:34 Edit Adj Rpt	S\$6,775.40 Edit Estimates	S\$6,775.40 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -				
Main Claimant:	MR ONG HOE HUP , ID: S1804748I				
Vehicle Reg. No.:	SLS2202D			Date of Loss:	06/03/2020 13:00 - :59 [28 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM20D202253/C02/LOWCT			Policy/Cover Note No.:	DMCVSN19303019000
Vehicle Reg. No. (Insured):	YM6100R			Policy No. (Claimant):	
				Excess:	S\$0.00
Repairer:	Trans Eurokars Pte Ltd (Ubi) 5 Ubi Close, 408605 Ubi - Tel:				
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Cecilia Low - 63896530]				
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 13/07/2020]				
Adj Asg. Remarks:	survey revert				

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SLS2202D (SNM20D202253/C02/LOWCT)**
[YM6100R]
TP
MR ONG HOE HUP
Mar 6 2020 1:00PM
[-]
Trans Eurokars Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports					1 per page	☒
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)		Thumbnail	Print	
1	06/03/20 16:55	Accident Statement		Load HTM		
2	26/06/20 08:43	Addendum Sheet		Load TIF		
3	26/06/20 08:46	Accident Statement Addm. #1		Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	06/07/20 09:37	Adjuster Immediate Advice		Load HTM		
Photos/Images					3 per page	☒
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)		Thumbnail	Print	
1	06/03/20 16:54	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
2	06/03/20 16:54	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
3	06/03/20 16:54	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
4	06/03/20 16:54	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
5	06/03/20 16:54	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
6	06/03/20 16:54	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
7	06/03/20 16:54	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
8	06/03/20 16:54	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
9	06/03/20 16:54	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
10	06/03/20 16:54	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
11	06/03/20 16:54	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
12	06/03/20 16:54	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
13	06/03/20 16:54	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
14	06/03/20 16:54	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
15	06/03/20 16:54	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
16	06/03/20 16:54	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
17	26/06/20 08:44	POLICE INV RESULT [Linked Accident Report Documents]		Load JPG	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	30/09/20 21:01	General View		Load JPG	☒	
2	30/09/20 21:01	General View		Load JPG	☒	
3	30/09/20 21:01	General View		Load JPG	☒	
4	30/09/20 21:01	General View		Load JPG	☒	
5	30/09/20 21:01	General View		Load JPG	☒	

Assessment Reports			1 per page	✓
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
6	30/09/20 21:01	General View	 Load JPG	✓
7	30/09/20 21:01	General View	 Load JPG	✓
8	30/09/20 21:01	General View	 Load JPG	✓
9	30/09/20 21:01	General View	 Load JPG	✓
10	30/09/20 21:01	General View	 Load JPG	✓
11	30/09/20 21:01	General View	 Load JPG	✓
12	30/09/20 21:01	General View	 Load JPG	✓
13	30/09/20 21:01	General View	 Load JPG	✓
14	30/09/20 21:01	General View	 Load JPG	✓
15	30/09/20 21:01	General View	 Load JPG	✓
16	30/09/20 21:01	General View	 Load JPG	✓
Documentation			1 per page	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/07/20 12:34	Pre-Repair Survey	 Load PDF	
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	06/03/20 16:50	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	26/06/20 08:45	POLICE REPORT [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	✓
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	06/03/20 16:55	Accident Statement	 Load HTM	
2	26/06/20 08:43	Addendum Sheet	 Load TIF	
3	26/06/20 08:46	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	✓
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	06/03/20 16:54	Accident Photo	 Load JPG	✓
2	06/03/20 16:54	Accident Photo	 Load JPG	✓
3	06/03/20 16:54	Accident Photo	 Load JPG	✓
4	06/03/20 16:54	Accident Photo	 Load JPG	✓
5	06/03/20 16:54	Accident Photo	 Load JPG	✓
6	06/03/20 16:54	Accident Photo	 Load JPG	✓
7	06/03/20 16:54	Accident Photo	 Load JPG	✓
8	06/03/20 16:54	Accident Photo	 Load JPG	✓
9	06/03/20 16:54	Accident Photo	 Load JPG	✓
10	06/03/20 16:54	Accident Photo	 Load JPG	✓
11	06/03/20 16:54	Accident Photo	 Load JPG	✓
12	06/03/20 16:54	Accident Photo	 Load JPG	✓
13	06/03/20 16:54	Accident Photo	 Load JPG	✓
14	06/03/20 16:54	Accident Photo	 Load JPG	✓
15	06/03/20 16:54	Accident Photo	 Load JPG	✓
16	06/03/20 16:54	Accident Photo	 Load JPG	✓
17	26/06/20 08:44	POLICE INV RESULT	 Load JPG	✓
Documentation			1 per page	✓
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print

Assessment Reports				1 per page	☒
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)		Thumbnail	Print
1	06/03/20 16:50	Sketch Plan		Load TIF	
2	26/06/20 08:45	POLICE REPORT		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20006911/AQF3S2**Date:** 15/10/2020REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN19303019000

Claimant Vehicle No : SLS2202D **Insured Vehicle No :** YM6100R

Date of Loss: 06/03/2020 Nature of Claim: TP Claim No: SNM20D202253/C02/LOWCT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS2202D**

Make & Model: MAZDA CX-5, 2.0 (A) Engine No: PY21047783

Reg. Date: 26/10/2017 (Man. Year: 2017) Chassis No: JM6KF2WLAJ0130202

Colour: Bronze Odometer: 56235 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R19 Rear Tyre Size: 225/55 R19

Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,991.60	4,225.40	1,766.20	29.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,655.00	2,550.00	4,105.00	61.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,646.60	6,775.40	5,871.20	46.43
+ GST 7.00/7.00% (S\$)	885.26	474.28	410.98	46.42
Nett Amount (S\$)	13,531.86	7,249.68	6,282.18	46.43

INSPECTION

Date of Assignment: 02/07/2020

Date Inspected: 03/07/2020 Inspected At: Trans Eurokars Pte Ltd (Ubi)
5 Ubi Close
Singapore 408605

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Oct 2020)
Parts:	M1-SUV	MAZDA CX-5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS2202D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,023.10 F	*- F
2	1		*RETAINER RHS	Not Necessary	15.50 F	*- F
3	2		*CLIP, FRONT BUMPER	Necessary	20.40 F	*20.40 F
4	5		*FASTENER, FRONT BUMPER	Necessary	15.00 F	*15.00 F
5	2		*RIVET, LICENCE PLATE	Not Necessary	15.20 F	*- F
6	1		*CHROME RHS	Not Necessary	152.80 F	*- F
7	8		*FASTENER, GRILLE TOP	Not Necessary	25.60 F	*- F
8	2		*PIN LOCATOR, FRONT GRILLE	Not Necessary	5.80 F	*- F
9	2		*GROMMET, FRONT GRILLE	Not Necessary	5.80 F	*- F
10	1		*CLIP, FRONT GRILLE	Not Necessary	13.70 F	*- F
11	8		*RIVET, GRILLE TOP	Not Necessary	73.60 F	*- F
12	14		*RIVET, GRILLE TOP	Not Necessary	56.00 F	*- F
13	1		*FRONT FENDER RHS	Dented	380.10 F	*380.10 F
14	1		*STAY RHS, FRONT FENDER	Necessary	51.30 F	*51.30 F
15	1		*MUDGUARD RHS	Not Necessary	98.20 F	*- F
16	1		*GARNISH RHS, FENDER	Deformed	158.30 F	*158.30 F
17	1		*HEADLAMP RHS	Necessary	3,565.60 F	*3,565.60 F
18	2		*CLIP, HEADLAMP	Necessary	13.00 F	*13.00 F
19	1		*RIVET, HEADLAMP	Necessary	3.50 F	*3.50 F
20	1		*RETAINER SIDE RHS, SENSOR	Necessary	18.20 F	*18.20 F
21	1		*SENSOR SIDE RHS, ULTRASONIC	Not Necessary	180.90 F	*- F
22	1		*SUNDRIES	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **5,991.60** **4,225.40**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER AND FRONT FENDER RH, REPAIR BONNET, FRONT DOOR RH AND ALL AREAS AFFECTED BY THE ACCIDENT.	New	2,970.00	990.00
2	TO RESPRAY FRONT BUMPER, BONNET, FRONT DOOR RH AND FRONT FENDER RH.	New	2,835.00	1,260.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	New	250.00	120.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION.	New	250.00	0.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	New	350.00	180.00
Gross Labour Cost (\$\$)			6,655.00	2,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >