

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

2-Jul-20

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6418 D

1 pc	Rear bumper
1 pc	Rear bumper lower cover
1 pc	Rear bumper inner sponge
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00
1 pc	Rear bumper reinforcement
2 pcs	Rear bumper stay o/s & n/s @ \$53.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00

\$	696.00	de
\$	206.00	ant
\$	114.00	X
\$	58.00	X
\$	607.00	2
\$	108.00	X
\$	36.00	X
\$	36.00	X
\$	1,861.00	902
\$	186.10	811.80.
\$	1,674.90	

### S/NETT

1 set	Rear bumper clips
1 set	Reverse sensor
1 set	Bootlid stickers
	Sundry

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$	48.00	30
\$	280.00	200 X un.
\$	100.00	X un
\$	50.00	10

To dismantle / replace reverse sensor to new bumper and reset to the same

\$	120.00	30
----	--------	----

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$	180.00	X un
----	--------	------

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc

811.80

470

1281.80

\$	650.00	200
----	--------	-----

To putty and spray painting on rear bumper, end panel, bootlid lower garnish

1/5 1600  
2 days

\$	600.00	200
----	--------	-----

To apply rustproofing on the repaired and replaced panels.

\$	80.00	X un
----	-------	------

\$ 3,782.90

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tanpin 97495749  
up 6/7/2011  
Insurance  
Resurvey after repair  
02 days  
tanpin @ lkk auto con.