



**TeamWork Garage Pte Ltd**  
 53 Ubi Avenue 1 #01-23/24 Spore 408934  
 Paya Ubi Industrial Park  
 Tel : 6844 2475

Steve (LKK) with parts  
 6 days LIS  
 Pte Ltd  
 16/4/19  
 5.45pm

X keep reference

E-mail : claims@teamworkgarage.com  
 Register number : 201015366H  
 Repair Performa Invoice

**United Overseas Insurance Limited**  
 3 Anson Road #28-01 Rly At Spg  
 Springleaf Tower  
 Singapore 079909

Vehicle number	SBV4067S
Make / Model	NISSAN/SUNNYB13
Chassis number	GA16205706B
Accident date	;27 March 2019
Reference	1904-03

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER / BR	570.00 ✓
1	BONNET / DD	891.00 ✓
1	FRONT SUPPORT PANEL / DD	550.00 ✓
1	FRONT RH WHEELHOUSE X R	420.00 X
1	FRONT RH FENDER / DD	510.00 ✓
		2941.00
	2521 -30% 1764.70	Less 30% 882.30
		2057.80
1	FRONT BUMPER BEAM X NN	156.00 X
2	FRONT BUMPER RETAINER X NN	42.00 X
1	FRONT BUMPER REINFORCEMENT X RPT	312.00 X
1	FRONT GRILLE ? ✓ BR	368.00 223 ✓
1	FRONT GRILLE EMBLEM ? ✓ NEC	35.00 ✓
2/1	FRONT HEADLAMP RH BR LH X NN	691.00 345.50 ✓
1	BONNET LOCK ? X NN	139.00 X
2/1	BONNET HINGE RH BT LH-R	110.00 55 ✓
1	FRONT RH FENDER INNER SHIELD / TN	90.00 ✓
1	WASHET TANK X NN	98.00 X
1	CONSENER ASSY X NN	890.00 X
1	RADIATOR ASSY X BR (not consistent)	1100.00 X
1	FRONT RH SHOCK ABSORBER X NN	519.00 X
1	FRONT RH KNCKLE ARM X NN	339.00 X
1	FRONT RH KNUCKLE BEARNG X NN	162.00 X
1	FRONT RH LOWER ARM X NN	240.00 X
		5291.00
	748.50 -10% 673.65	Less 10 % Subtotal 4761.90
		Balance C/F 4761.90

PARTS REPLACEMENT - SPECIAL NETT ITEMS

		Balance B/F	4761.90
1 SET	FRONT BUMPER CLIP <i>✓ A/EC</i>		<i>30</i> ✓ 40.00
1 SET	FRONT FENDER INNER TRIM CLIP <i>✓ A/EC</i>		<i>30</i> ✓ 30.00
1	RIM <i>× NN</i>		600.00 ×
1 BOT	BRKE FUILD <i>× NN</i>		50.00 ×
1 BOT	COOLANT <i>× NN</i>	50	60.00 ×
		Subtotal	780.00
		Balance C/F	7599.70
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
		Balance B/F	7599.70
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM		<i>30</i> 60.00
2	REMOVE,RENEW CIONDENSER AND TOP UP GAS		<del>X</del> 150.00 120 ✓
3	REMOVE, RENEW RADIATOR AND TOP UP COOLANT		<i>X</i> 150.00
4	CHECK FRONT WHEEL ALIGNMENT		<i>X</i> 150.00
5	REMOVE AND REPLACE FRONT WHEEL ALIGNMENT		<i>X</i> 200.00
6	PANEL BEATING ON AFFECTED AREAS		<i>700 600</i> 1000.00
7	SPRAY PAINTING ON AFFECTED AREAS		<i>800</i> 900.00
		1650	
		Subtotal	2610.00
		Grand total	10209.70
			10,210.60#

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

P - 2438.35  
N - 50  
L - 1650  
4138.35

L/S - 3310.68  
= 3300