



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2202610

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 09/05/2022
Reference CC6/CTI20006917/Kea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. YN 7429G
Insured Veh. PC 4720Z
Claim No. SNM19D202975
Policy No. DMB1SN3063731800
Accident Date 24/06/2019
Inspection Date 01/07/2020

Description	Total
Survey Inspection	350.00
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI20006917/Kea3q2 Date: 09/05/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 4720Z	Veh. Inspected	YN 7429G	
Policy No.	DMB1SN3063731800	Coverage (\$)	0.00	
Claim No.	SNM19D202975	Excess (\$)	0.00	
Assign From		Assign Date	01/07/2020	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	FEB21EA01085	Colour	WHITE	
Odometer	158381 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	BRIDGESTONE	8 mm	
L/H Front Tyre	195 R15X8	BRIDGESTONE	8 mm	
R/H Rear Tyre	195 R15X8 (D)	BRIDGESTONE	8/8 mm	
L/H Rear Tyre	195 R15X8 (D)	BRIDGESTONE	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/06/2019	Inspection Date	01/07/2020	
Survey held at	K KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE #02-20 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 7429G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	N/S FRONT DOOR	BENT	1,910.15	1,910.15
1	N/S FRONT DOOR OUTER PULL HADLE	DISTORTED	105.86	105.86
1	N/S FRONT DOOR ARCH GARNISH	DISTORTED	68.04	68.04
1	N/S CABIN REAR OUTER PANEL	BENT	604.85	604.85
1	N/S SIDE GATE	BENT	4,734.97	4,734.97
1	N/S SIDE GATE FRONT SAFETY LOCK	BENT	194.10	194.10
1	N/S SIDE GATE RUBBER STOPPER	MISSING	25.00	25.00
	LESS 20% DISCOUNT		-1,528.59	-1,528.59
			6,114.38	6,114.38
	<u>SPECIAL NETT ITEMS</u>			
1	N/S FRONT DOOR COMPANY STICKER (SN)	NECESSARY	240.00	180.00
1	N/S SIDE GATE COMPANY STICKER (SN)	NECESSARY	120.00	80.00
			360.00	260.00
	<u>LABOUR</u>			
	TO REMOVE ,CUT OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.		700.00	600.00
	TO REMOVE DOOR'S FITTINGS.		80.00	60.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		800.00	700.00
			1,580.00	1,360.00
	GRAND TOTAL		8,054.38	7,734.38
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,150.00

Report Ref No. CC6/CTI20006917/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YN 7429G

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

