

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : PC 4720 Z
Accident Date : 24-Jun-2019

No. : 31214

Date : 30-Jun-2020

Our Ref : 020264 (CHINA) / QUEK

PAGE : 1

ROAD BUILDERS SINGAPORE PTE LTD
Singapore

*Not Authorised
61 Day @ 6150h
Repair After Paint 6 days*

ESTIMATED COST OF REPAIR FOR MIT CANTER FEB21 (2998cc)(2015) YN7429G
=====

1 pc	n/s front door	1,910.15	✓
1 pc	n/s front door outer pull handle	105.86	✓
1 pc	n/s front door arch garnish	68.04	✓
1 pc	n/s cabin rear outer panel	604.85	✓
1 pc	n/s side gate	4,734.97	✓
1 pc	n/s side gate front safety lock	194.10	✓
1 pc	n/s side gate rubber stopper	25.00	✓
		7,642.97	
Less 20% :		-1,528.59	
		6,114.38	

1 pc n/s front door company sticker
1 pc n/s side gate company sticker

1800h
240.00 sn
120.00 sn *2000h*

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

700.00 *600h*

To remove door's fittings

80.00 *60h*

To putty and respray on affected portions.

800.00 *700h*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total : S\$ 8,054.38
=====

Singapore Dollars Eight Thousand and Fifty Four and Cents Thirty Eight Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.