

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 06 Jul 2020

Preliminary Advice

Insured Vehicle No	: SLV9621R	Accident Date	: 30/06/2020
TP Vehicle No	: FBK2948X	Assignment Date	: 02/07/2020
Make	: YAMAHA YBR125	Est. Duration of Repair	: 3
Date of Inspection	: 3/7/2020		
Inspection At	: BAN HOCK HIN CO.PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,293.29
Revised Amount	:S\$	3,640.30
Check Items (Estimated)	:S\$	277.20
Total	:S\$	3,917.50

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The above survey was conducted on a 'Without Prejudice' basis.