LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From:

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Pauline Tham Date: 17 Aug 2020

Preliminary Advice

Insured Vehicle No : SMQ7798S

TP Vehicle No : SKU244Y Accident Date : 26/06/2020
Make : KIA SORENTO Assignment Date : 17/08/2020

Date of Inspection : 03/07/2020 Est. Duration of Repair : 4

Inspection At : ETHOZ GROUP LTD (HQ)

30 BUKIT BATOK CRÈSCENT

SINGAPORE 658075

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear and parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 2,665.11 |
|-----------------------------|------|----------|
| Revised Amount | :S\$ | 1,591.69 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 1,591.69 |

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

Remarks

| (|) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. |
|---|---|--|
| | | Kindly let us have your authorisation. |
| | | |

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: The above survey was conduct without "prejudice" basis