

DETAILS

Reference

Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Jul 2020)
 Parts: M1-SUV PEUGEOT 3008 ALLURE 1.6 E-THP EAT6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Goldbell Engineering Pte Ltd/SLZ6794Z/01/07/2020 18:04
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET 450	0.00	0.00	2,395.37 F ✓
2	1		*BONNET HINGE LH	R 0.00	0.00	464.61 F ✓
3	1		*BONNET HINGE RH	R 0.00	0.00	464.61 F ✓
4	1		*BONNET INSULATOR 155	0.00	0.00	530.26 F ✓
5	1		*FRONT GRILL	Sm 0.00	0.00	407.84 F ✓
6	1		*FRONT GRILL CHROME MOULDING	Sm 0.00	0.00	407.84 F ✓
7	1		*FRONT EMBLEM	Sm 0.00	0.00	407.84 F ✓
8	1		*FRONT BUMPER 850	At/cm 0.00	0.00	2,000.12 F ✓
9	1		*FRONT BUMPER RETAINER LH 85	cm 0.00	0.00	102.77 F ✓
10	1		*FRONT BUMPER SIDE BRACKET LH	R 0.00	0.00	424.00 F ✓
11	1		*FRONT BUMPER LOWER CORNER COVER LH 195	0.00	0.00	535.06 F ✓
12	1		*FRONT BUMPER SPONGE	Sm 0.00	0.00	464.61 F ✓
13	1		*FRONT BUMPER REINFORCEMENT	R 0.00	0.00	464.61 F ✓
14	1		*FRONT SUPPORT PANEL	R 0.00	0.00	464.61 F ✓
15	1		*LH HEADLAMP 1100	R 0.00	0.00	1,969.12 F ✓
16	1		*LH HEADLAMP LOWER BRACKET	R 0.00	0.00	400.00 F ✓
17	1		*LH FRONT FOG LAMP 180	CR 0.00	0.00	550.72 F ✓
18	1		*LH FRONT FOG LAMP COVER 85	0.00	0.00	447.33 F ✓
19	1		*LH FRONT FOG LAMP CHROME MOULDING	0.00	0.00	407.84 F ✓
20	1		*LH FRONT FENDER 355	R 0.00	0.00	927.52 F ✓
21	1		*LH FRONT FENDER INNER PANEL	0.00	0.00	704.00 F ✓
22	1		*LH FRONT FENDER LOGO 118.37	0.00	0.00	118.27 F ✓
23	1		*LH FRONT FENDER INNER SHIELD 115	0.00	0.00	464.07 F ✓
24	1		*LH FRONT FENDER ARCH GARNISH 300	Di/cm 0.00	0.00	497.86 F ✓
25	1		*LH FRONT DOOR	R 0.00	0.00	2,604.07 F ✓
26	1		*LH FRONT DOOR PROTECTOR	Sm 0.00	0.00	510.47 F ✓
27	1		*LH CHASSIS	R 0.00	0.00	8,000.00 F ✓
28	1		*LH FRONT WHEEL HOUSE	R 0.00	0.00	620.00 F ✓
29	1		*RESONATOR BOX	Sm 0.00	0.00	408.00 F ✓
30	1		*CONDENSOR	Sm 0.00	0.00	1,304.22 F ✓
31	1		*RADIATOR	Sm 0.00	0.00	2,140.02 F ✓
32	1		*RADIATOR FAN COWLING	Sm 0.00	0.00	750.00 F ✓
33	1		*RADIATOR FAN MOTOR	Sm 0.00	0.00	457.70 F ✓
34	1		*RADIATOR FAN BLADE	Sm 0.00	0.00	1300.00 F ✓
35	1		*LH SIDE ROCKER PANEL	R 0.00	0.00	4,060.57 F ✓
36	1		*IMPACT SENSOR LH 350	0.00	0.00	302.72 F ✓
37	1		*IMPACT SENSOR RH 350	0.00	0.00	302.72 F ✓
38	1		*RH FRONT AIRBAG 3717.46	0.00	0.00	2,717.46 F ✓
39	1		*RH FRONT AIRBAG CLOCK SPRING 650	0.00	0.00	600.47 F ✓
40	1		*LH FRONT AIRBAG 3097.37	0.00	0.00	3,097.37 F ✓
41	1		*FRONT DASHBOARD 6200	0.00	0.00	2,763.96 F ✓
42	1		*AIRBAG CONTROL UNIT 940	0.00	0.00	2,937.72 F ✓
43	1		*FRONT SEAT BELT LH 950	0.00	0.00	927.52 F ✓
44	1		*FRONT SEAT BELT RH 950	0.00	0.00	927.52 F ✓
45	1		*FRONT SEAT BELT BUCKLE LH 480	0.00	0.00	770.51 F ✓

Goldbell Engineering Pte Ltd/SLZ6794Z/01/07/2020 18:04. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Scanned with CamScanner

Scanned with CamScanner

Part No.	Particulars	%Disc	%Depr	Amount
	*FRONT SEAT BELT BUCKLE RH 480	7m	0.00	0.00
48 1	*LH ABS SENSOR 85	M	0.00	0.00
49 1	*LH FRONT ABSORBER 145		0.00	0.00
50 1	*LH FRONT KNUCKLE ARM 440		0.00	0.00
51 1	*LH FRONT LOWER ARM 180		0.00	0.00
52 1	*LH FRONT WHEEL HUB	Sm	0.00	0.00
53 1	*LH FRONT WHEEL HUB BEARING	Sm	0.00	0.00
54 1	*LH FRONT TIE ROD	Sm	0.00	0.00
55 1	*LH FRONT TIE ROD END	Sm	0.00	0.00
56 1	*LH FRONT STABILIER LINGKAGE	Sm	0.00	0.00
57 1	*LH FRONT DRIVE SHAFT	R	0.00	0.00
58 1	*FRONT CROSSMEMBER	Sm	0.00	0.00
59 1	*STEERING RACK AND PINION	R	0.00	0.00
	*FRONT SENSOR HARNESS	Sm	0.00	0.00

F=Franchise part.

Total Parts (S\$) 59,559.54

Goldbell Engineering Pte Ltd/SLZ6794Z/01/07/2020 18:04. Not valid without Reference section.
Generated using Merlimen e-Claims IEAS

Scanned with CamScanner

Scanned with CamScanner

es on Miscellaneous Items

Particulars

Amount

Miscellaneous Items

1	1	BONNET INSULATOR CLIPS
2	1	COOLANT
3	1	FRONT BUMPER CLIPS
4	1	FRONT BUMPER SENSOR (SET)
5	1	FRONT GRILLE CLIPS
6	1	FRONT LOWER BUMPER SENSOR WITH HOLDER AND SEAL (SET)
7	1	FRONT NUMBER PLATE
8	1	LH FRONT FENDER ARCH GARNISH CLIPS
9	1	LH FRONT FENDER INNER SHEILD CLIPS
10	1	LH FRONT LIM
11	1	LH FRONT TYRE
12	1	TOWING

nc	50.00	2
nn	50.00	2
nc	50.00	✓
mi	600.00	✓
nn	30.00	X
st	1,020.00	2
nc	50.00	✓
nc	30.00	✓
nc	1,050.00	✓
mi	550.00	280.00
(8:11)	100.00	2

Sub Total (SS) 3,630.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P: \$22,383.10

S/N: \$3500.00 3390

L: \$6,450.00 6320

S: \$8,802.31

\$41,135.41

40,895.41

Scanned with CamScanner

Scanned with CamScanner

Estimates on Labour

Particulars	Lab.Type	Amount
Labour Items	0600	3000
1 TO REMOVE, REFIX & REPAIR AFFECTED DAMAGED PARTS, INCLUDING KNOCK OUT, WELD AND STRAIGHTEN ON THE AFFECTED PARTS	New	4,800.00
2 TO REMOVE AND REFIT LH FRONT UNDERCARRIAGE AND CROSSMEMBER	New	300 350.00
3 TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	150.00
4 TO ROTATE AND BALANCING LH FRONT WHEEL	New	100.00 201
5 TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	200.00 201
6 TO REMOVE AND REFIT FRONT SENSOR	New	120.00 601
7 TO RESET AIRBAG WARNING LIGHT	New	350.00 2001
8 TO REMOVE AND REFIT RH FRONT AIRBAG	New	350.00 3204
9 TO REMOVE AND REFIT LH FRONT AIRBAG	New	450.00
10 TO REMOVE AND REFIT FRONT DASHBOARD	New	350.00 3002
11 TO REMOVE AND REFIT FRONT SEATS BELT AND BUCKLE	New	350.00 1301
12 TO REMOVE AND REFIT AIRCON CONDENSOR	New	450.00 2
13 TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC 0350	New	1750 2,500.00
14 TO REMOVE AND RESET ABS WARNING LIGHT	New	150.00 1001
15 TO REPAIR AND STRAIGHTEN FRONT FRAME CHASSIS	New	250 300.00 ?
Gross Labour Cost (\$\$)		10,750.00

Goldbell Engineering Pte Ltd/SLZ6794Z/01/07/2020 18:04. Not valid without Reference section.
Generated using Merlmen e-Claims IEAS

< END OF ESTIMATES >



REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 11 Jul 2020)**Parts:** M1-SUV PEUGEOT 3008 ALLURE 1.6 E-THP EAT6 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Goldbell Engineering Pte Ltd/SLZ6794Z/11/07/2020 13:39**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR SEAT BELT LH	<i>Jm</i> 0.00	0.00	*1,071.00 F ✓
2	1		*REAR SEAT BELT RH	<i>Jm</i> 0.00	0.00	*1,071.00 F ✓
3	1		*REAR SEAT BELT CENTER	<i>Sm</i> 0.00	0.00	*943.50 F ✓
4	1		*REAR SEAT BELT BUCKLE LH	<i>Jm</i> 0.00	0.00	*493.50 F ✓
5	1		*REAR SEAT BELT BUCKLE RH	<i>Jm</i> 0.00	0.00	*546.00 F ✓
6	1		*FUSE BOX	<i>CM</i> 0.00	0.00	*393.75 F ✓
7	1		*FUSE BOX COVER	<i>DM</i> 0.00	0.00	*278.25 F ✓
Total Parts (S\$)						3,853.50 4,767.00

F=Franchise part.

Goldbell Engineering Pte Ltd/SLZ6794Z/11/07/2020 13:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jul 2020)

Parts: M1-SUV PEUGEOT 3008 ALLURE 1.6 E-THP EAT6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Goldbell Engineering Pte Ltd/SLZ6794Z/14/07/2020 12:52

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*SUBFRAME	0.00	0.00	<i>B7</i> *3,517.50 F ✓
Total Parts (S\$)						3,517.50

Goldbell Engineering Pte Ltd/SLZ6794Z/14/07/2020 12:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Sep 2020)

Parts: M1-SUV PEUGEOT 3008 ALLURE 1.6 E-THP EAT6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Goldbell Engineering Pte Ltd/SLZ6794Z/15/09/2020 19:47

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*GEAR CONTROL UNIT	0.00	0.00	<i>mc</i> *981.31 F ✓
2	1		*LH SIDE MIRROR ASSY	0.00	0.00	<i>cm</i> *450.00 F ✓
Total Parts (S\$)						1,431.31

F=Franchise part.

Goldbell Engineering Pte Ltd/SLZ6794Z/15/09/2020 19:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS