

SJH 4445A.

Toyota Allion. 1496 cc

NZT2603028503

LKK Auto Consultants hence notify

The Repairer of the following:

- To remove and spray painting
- To repair damage to parts during survey
- Parts breakdowns, or the replacement
- Third party survey is in a written Prevalence basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by ~~855~~ 855 ✓

Signature:

Date:

30 ✓

Rear Bumper Deformed

Rear Bumper Clips. new

Rear Bumper Side Holder x02 new

Rear Bumper Reflector x02 Hatched

Rear Bumper Impact Bracket x02 Hatched

Reverse Sensor Dazed

Rear End Panel Dented

Rear End Panel Top Garnish. Deformed

Rear End Panel Sealant. new

Taillamp x02 Cinked

Taillamp Panel x02 Rep. 5

Bootlid Dented

Bootlid Lock Dazed

Bootlid Lock Antenna Cinked

Bootlid Weatherstripe. New

Toyota Logo. New

Spare Tyre Panel Top Cover Deformed

Rear Exhaust Pipe

Rear Exhaust Mounting. $\left. \begin{matrix} 2 \\ \text{New} \end{matrix} \right\}$

Rear Camera.

68x2 = 136 ✓

113.8x2 = 227.60 113.80

63.2x2 = 126.40 63.20

280(SN) / 200(SN)

508.20 ✓

281 ✓

60(SN) ✓

378.5x2 = 757 ✓

231x2 = 462 X

951.60 ✓

323.40 ✓

157.40 ✓

229.10 X

59.40 ✓

292.80 ✓

796.10 X 4528.80

35.40 X 3386.60

480(SN) X SN.260

Panel Banting

Spray Painting.

To remove reverse sensor

To remove rear camera.

To remove upholstery

To remove exhaust pipe

To undersend.

To transfer bootlid fittings. $\left. \begin{matrix} 200 \\ \text{New} \end{matrix} \right\}$

1200 8W

1200 8W 1880

100 50

100 50

150 60

150 X

150 60

150 60

total: 55366

4/8 44K

OT Days

8606.25

\$10,248.40