

SJH 4445A.
Toyota Allion. 1496 cc
NZT2603028503

LKK Auto Consultants hence notify
the Repairer of the following:

- To rectify and spray painting
- To rectify and repaints during survey
- To rectify and repaints during survey
- Third party survey is in a without Prejudice basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by ~~855~~ 855 ✓
Signature: _____
Date: 30 ✓

Rear Bumper Deformed		
Rear Bumper Clips. new		
Rear Bumper Side Holder x02 new	68x2 = 136 ✓	
Rear Bumper Reflector x02 Hatched	113.8x2 = 227.60	113.80
Rear Bumper Impact Bracket x02 Hatched	63.2x2 = 126.40	63.20
Reverse Sensor Dazed	280 (SN) / 200 (SN)	
Rear End Panel Dented	508.20 ✓	
Rear End Panel Top Garnish. Deformed	281 ✓	
Rear End Panel Sealant. new	60 (SN) ✓	
Taillamp x02 Cinked	378.5x2 = 757 ✓	
Taillamp Panel x02 Rep. 5	231x2 = 462 X	
Bootlid Dented	951.60 ✓	
Bootlid Lock Dazed	323.40 ✓	
Bootlid Lock Antenna Cinked	157.40 ✓	
Bootlid Weatherstripe. new	229.10 X	
Toyota Logo. New	59.40 ✓	
Spare Tyre Panel Top Cover Deformed	292.80 ✓	
Rear Exhaust Pipe	796.10 X	4528.80
Rear Exhaust Mounting. 2 new	35.40 X	3386.60
Rear Camera.	480 (SN) X	SN. 260
Panel Beating	1200 8w	
Spray Painting.	1200 8w	1880
To remove reverse sensor	100 50	
To remove rear camera.	100 50	
To remove upholstery	150 60	total: 55366
To remove exhaust pipe	150 X	4/8 44K
To undersend.	150 60	OT Days
To transfer bootlid fittings. 200	150 60	8606.25