

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Feb 2015 14:46 Edit Reg		03 Feb 2015 00:00 Edit Adj Rpt	S\$3,634.98 Edit Estimates	S\$3,634.98 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	SIN LIAN SENG TRADING CO , Co. Reg. No.: -, Tel: +6581210858		
Main Claimant:	TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHC5950P	Date of Loss:	31/01/2015 13:00 - :59 [1 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0997354825SG	Policy/Cover Note No.:	0100247657 Coverage: 27/08/2014 - 26/08/2015
Vehicle Reg. No. (Insured):	GV6263U	Policy No. (Claimant):	D-12047359MFSH/
		Excess:	
Repairer:	Trans-cab Auto Services Pte Ltd (HQ) No. 42 Sungei Kadut St 1, 729346 Sungei Kadut - Tel: 62876666		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Rparthiban, Theerthan] Theerthan.Parthiban@aig.com		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 03/08/2020]		
Driver/Custodian (Insured):	GOH BOON PHIAW (), NRIC: S0642878I Email:		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (11/11/2020): **Alert - Adj Mandate Approved (S\$4430.43) - SHC5950P - Claim Handler: Rparthiban,...**
- AIG_SG (29/07/2020): **Report Send Back Alerts - SHC5950P (TP)**
- AIG_SG (23/07/2015): **tp**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC5950P (0997354825SG)
[GV6263U]
TP
TRANS-CAB SERVICES PTE LTD
Jan 31 2015 1:00PM
[SIN LIAN SENG TRADING CO]
Trans-cab Auto Services Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser ▼
Letters/Correspondences						1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown			Edit	<input type="checkbox"/>
2	18/12/15 11:59	Insurer Offer Letter/DV <small>[Offer superseded on 2015/12/18]</small>			Load HTM	<input type="checkbox"/>
Photos/Images						3 per page ▼ <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	04/02/15 19:45	General View			Load JPG	<input checked="" type="checkbox"/>
2	04/02/15 19:45	General View			Load JPG	<input checked="" type="checkbox"/>
3	04/02/15 19:45	General View			Load JPG	<input checked="" type="checkbox"/>
4	04/02/15 19:45	General View			Load JPG	<input checked="" type="checkbox"/>
5	04/02/15 19:45	General View			Load JPG	<input checked="" type="checkbox"/>
6	04/02/15 19:45	General View			Load JPG	<input checked="" type="checkbox"/>
7	04/02/15 19:45	General View			Load JPG	<input checked="" type="checkbox"/>
8	04/02/15 19:45	General View			Load JPG	<input checked="" type="checkbox"/>
9	04/02/15 19:45	General View			Load JPG	<input checked="" type="checkbox"/>
10	04/02/15 19:45	General View			Load JPG	<input checked="" type="checkbox"/>
11	04/02/15 19:45	Odometer Reading			Load JPG	<input checked="" type="checkbox"/>
12	04/02/15 19:45	Chassis Number			Load JPG	<input checked="" type="checkbox"/>
13	04/02/15 19:45	General View			Load JPG	<input checked="" type="checkbox"/>
14	04/02/15 19:45	General View			Load JPG	<input checked="" type="checkbox"/>
Documentation						1 per page ▼ <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	04/02/15 19:44	TP ESTIMATE			Load PDF	<input type="checkbox"/>
2	04/02/15 19:44	TP GIA & POLICE REPORT			Load PDF	<input type="checkbox"/>
3	14/12/15 17:42	APPROVAL TO WP			Load PDF	<input type="checkbox"/>
4	16/12/15 15:27	LETTER TO OI			Load PDF	<input type="checkbox"/>
5	11/11/20 10:40	LOD,REPAIR BILL,MILEAGE RECORD, ATA,LTA SEARCH			Load PDF	<input type="checkbox"/>
6	11/11/20 10:40	WITNESS STATEMENT			Load PDF	<input type="checkbox"/>
7	11/11/20 10:43	EMAIL FROM AIG DD 2310202			Load PDF	<input type="checkbox"/>
8	17/11/20 15:00	Authorisation to Act			Load PDF	<input type="checkbox"/>
9	17/11/20 15:00	LTA SEARCH			Load PDF	<input type="checkbox"/>
10	17/11/20 15:00	Release Voucher			Load PDF	<input type="checkbox"/>
11	17/11/20 15:00	RENTAL MILEAGE			Load PDF	<input type="checkbox"/>
12	17/11/20 15:00	RENTAL RECEIPT			Load PDF	<input type="checkbox"/>
13	17/11/20 15:00	WORKSHOP INVOICE			Load PDF	<input type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)			Thumbnail	Print
1	04/02/15 16:56	OI GIA REPORT			Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	GV6263U (Insd veh)	Model:	RENAULT LATITUDE 2.0 D DCI (A)
	SHC5950P (TP veh)		
Date of Accident:	31/01/2015		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:\$		18,519.45
Final Repair Cost	:\$		2,218.00
Loss of Use	:\$		_____ days at \$0.00 per day
Rental (if any)	:\$		4 days
LTA / GIA Search Fee	:\$		
Others:	:\$		
	:\$		
Final Settlement Sum (GLOBAL SUM)	:\$		2,218.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u>:		Agreed Liability _____ 50 _____ (%)	
B) For <u>GIA Registered Workshop</u>:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Trans-Cab Auto Services Pte Ltd	:\$	2,218.00
2)		:\$	
3)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

17 Nov
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG15002074/KKA3S2-1
Date: 17/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0100247657
Claimant Vehicle No : SHC5950P **Insured Vehicle No :** GV6263U
Date of Loss: 31/01/2015 Nature of Claim: TP Claim No: 0997354825SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5950P**
Make & Model: RENAULT LATITUDE, 2.0 D dCi (A) Engine No: M9R8839C002160
Reg. Date: 18/12/2014 (Man. Year: 2014) Chassis No: VF1ABL15AUC280986
Colour: Metallic White/Red Odometer: 16254 km
Engine Capacity: 1995 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: Goodyear 9 mm Rear Left Side: Goodyear 8 mm
Front Right Side: Goodyear 9 mm Rear Right Side: Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,487.90	2,319.98	8,167.92	77.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,820.00	1,315.00	5,505.00	80.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,307.90	3,634.98	13,672.92	79.00
+ GST 7.00/7.00% (S\$)	1,211.55	254.45	957.10	79.00
Nett Amount (S\$)	18,519.45	3,889.43	14,630.02	79.00
+ Car Rental (4.0 x S\$133.75/day) (S\$)		535.00		
		(S\$)		
		4,424.43		
Liabile Amount (50.00%) (S\$)		2,212.22		
+ Doc/Search Fee (S\$)		6.00		
Nett Liability (S\$)		2,218.22		
Global Sum Settlement (S\$)		2,218.00		

INSPECTION

Date of Assignment: 03/02/2015
Date Inspected: 03/02/2015 Inspected At: Trans-cab Auto Services Pte Ltd (HQ)
No. 42 Sungei Kadut St 1
Singapore 729346
Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Cracked	807.32 FL	*807.32 FL
2	1		*BUMPER ABSORBER FRT	Serviceable	253.00 FL	*- FL
3	1		*BUMPER BEAM FRT	Repair	585.95 FL	*- FL
4	1		*BUMPER RETAINER FRT LH	Dented	97.06 FL	*97.06 FL
5	1		*BUMPER SUPPORT FRT LH	Serviceable	15.31 FL	*- FL
6	1		*BONNET	Repair	1,244.63 FL	*- FL
7	1		*AIR CLEANER LOWER	Serviceable	226.05 FL	*- FL
8	1		*STEERING PUMP ELECTRIC	Serviceable	1,285.90 FL	*- FL
9	1		*HEADLAMP LH	Serviceable	759.25 FL	*- FL
10	1		*FENDER PANEL FRT LH	Bent	502.46 FL	*502.46 FL
11	1		*FENDER WHEELARCH FRT LH	Serviceable	89.44 FL	*- FL
12	1		*LOWER ARM LH	Serviceable	439.59 FL	*- FL
13	1		*KNUCKLE ARM LH	Serviceable	542.94 FL	*- FL
14	1		*ABSORBER FRT LH	Serviceable	231.12 FL	*- FL
15	1		*DOOR MIRROR LH	Cracked	950.90 FL	*950.90 FL
16	1		*DOOR PANEL FRT LH	Repair	1,823.50 FL	*- FL
17	1		*DOOR SEAL FRT LH	Cut	46.68 FL	*46.68 FL
18	1		*ROCKER PANEL OUTER LH	Repair	633.01 FL	*- FL
19	1		*SET FRONT BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
20	1		*SET BUMPER RETAINER CLIP FRT LH	Not Necessary	15.20 FS	*- FS
21	1		*SET WHEELARCH CLIP LH	Not Necessary	66.00 FS	*- FS
22	1		*CAP HUB LH FRT	Serviceable	35.00 FS	*- FS
23	1		*RIM LH FRT	Serviceable	385.00 FS	*- FS
24	1		*TYRE LH FRT	Serviceable	330.00 FS	*- FS
25	1		*DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
26	1		*DOOR STICKER CLASSIC	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,541.31	2,560.42
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,053.41	240.44
Total Parts (\$\$)	10,487.90	2,319.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	2,800.00	500.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	15.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	3,000.00	660.00
4	TO TRASNFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	60.00
6	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
7	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	30.00
8	TOWING FEES.	New	120.00	50.00
			Gross Labour Cost (\$\$)	6,820.00
				1,315.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >