

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHC 5950P -

ROEL

Not Authorized
1-Bil
83634.98

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC 5950P - ROEL
 VF1ABL15AUC280986
 RENAULT
 LATITUDE
 31.01.15
 AG

PART		LIST
1	1 BUMPER COVER FRT	\$ <i>CRA</i> 807.32 ✓
2	1 BUMPER ABSORBER FRT	\$ <i>Sm</i> 253.00 X
3	1 BUMPER BEAM FRT	\$ <i>R</i> 585.95 X
4	1 BUMPER RETAINER FRT LH	\$ <i>nd</i> 97.06 ✓
5	1 BUMPER SUPPORT FRT LH	\$ <i>Sm</i> 15.31 X
6	1 BONNET	\$ <i>R</i> 1,244.63 X
7	1 AIR CLEANER LOWER	\$ <i>Sm</i> 226.05 X
8	1 STEERING PUMP ELECTRIC	\$ <i>Sm</i> 1,285.90 X
9	1 HEADLAMP LH	\$ <i>Sm</i> 759.25 X
10	1 FENDER PANEL FRT LH	\$ <i>Bt</i> 502.46 ✓
11	1 FENDER WHEELARCH FRT LH	\$ <i>Sm</i> 89.44 X
12	1 LOWER ARM LH	\$ <i>Sm</i> 439.59 X
13	1 KUNCKLE ARM LH	\$ <i>Sm</i> 542.94 X
14	1 ABSORBER FRT LH	\$ <i>Sm</i> 231.12 X
15	1 DOOR MIRROR LH	\$ <i>CRA</i> 950.90 ✓
16	1 DOOR PANEL FRT LH	\$ <i>R</i> 1,823.50 X
17	1 DOOR SEAL FRT LH	\$ <i>wt</i> 46.68 ✓
17	1 ROCKER PANEL OUTER LH	\$ <i>R</i> 633.01 X
TOTAL		\$ 10,534.11
10%		\$ 1,053.41
		\$ 9,480.70

Specical Nett

1SET	FRONT BUMPER CLIP	\$ <i>Sm</i> 66.00 ✓
1SET	BUMPER RETAINER CLIP FRT LH	\$ <i>Sm</i> 15.20 X
1SET	WHEELARCH CLIP (Necessary)LH	\$ <i>Sm</i> 66.00 X
1	CAP HUB LH FRT	\$ <i>Sm</i> 35.00 X
1	RIM LH FRT	\$ <i>Sm</i> 385.00 X
1	TYRE LH FRT	\$ <i>Sm</i> 330.00 X
1	DOOR STICKER "Trans-cab"	\$ <i>Sm</i> 80.00 ✓

1 DOOR STICKER "Classic" \$ *nr* 30.00 ✓

TOTAL \$ 1,007.20

TOTAL PARTS \$ 10,487.90

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same \$ 2,800.00 *500*

To Check Electrical Lighting Concerned. \$ 170.00 *150*

Putty and spray painting of the affected portion. \$ 3,000.00 *660*

To transfer of tire, rim and on wheel balancing. \$ *nr* 170.00 *X*

To check steering geometry and computer wheel alignment \$ 220.00 *600*

To transfer of door fittings, attachment and perform water seepage test. \$ *nr* 170.00 *X*

To rust-proofing of the affected areas. \$ 170.00 *300*

Towing Fees \$ 120.00 *500*

TOTAL \$ 6,700.00

Over All Total \$ 17,187.90

(PARTS BY PARTS) Repair Days 10 DAYS
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: