

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 39666

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0456/2020/NS
Date	:	30-Jun-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name Address

: Mr Sung Kuang (Song Gang)
: Blk 656A Jurong West Street 61
: #06-341

Singapore 641656

: +(65) 96659883

: Own Damage Claims

: 1800073873

: **SKJ 689 E**

: Audi A5 SB 2.0 TFS

: Jul-18

: CVK 064263

: WAUZZZF51JA112867

: -

: -

: Johnny Boo / Allan Wu

: 29-Jun-20

: Toh Guan Road (IMM Carpark Exit)

Telephone

Type of Claim

Policy No.

Vehicle No

Model Code

Model / Year

Engine No

Chassis No

Mileage

Date In

Estimated By

Accident Date

Place of Accident

Premium Automobiles

55 Ubi Road 1, Singapore 408695
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKJ 689 E

S/N	Nature of Jobs	S/N	\$	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer/reinstall front bumper wire harness for front parking aid system.	S/N	\$	280.00	✓
2	To dismantle and renew front bumper, bonnet and lhs headlight. To repair lhs front fender. Re-organise crash management components. Reinstall all parts removed. ✓ X ✓	\$		3,200.00 1250	
3	To respray front bumper, lhs front fender and bonnet.	\$		3,500.00 1100	
4	To carry out diagnostic check.	S/N	\$	192.00	✓
TOTAL LABOUR CHARGES				: \$ 7,172.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

SKJ 689E

Material List for Accident Vehicle Regn No. SFE26B

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/	Nett	
1	FRONT BUMPER	\$	2,142.00	✓
2	FRONT BUMPER FIXING PARTS	\$	383.00	X
3	FRONT BUMPER SECURING STRIP	\$	34.00	X
4	FRONT BUMPER GRILLE - CENTRE	\$	185.00	X
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$	215.00	X
6	FRONT BUMPER SPOILER	\$	504.00	X
7	FRONT BUMPER AIR GUIDE - LH	\$	59.00	2nd ?
8	RADIATOR GRILLE	\$	2,190.00	X
9	SULTRASOUND SENSOR SUPPORT - LH / RH	\$	98.00	X
10	RADIATOR GRILLE COVER - UPPER	\$	178.00	X
11	FRONT BUMPER AIR GUIDE GRILLE - LH	\$	446.00	✓
12	FRONT BUMPER CARRIER	\$	757.00	?
13	FRONT BUMPER GUIDE SECTION - LH	\$	34.00	X
14	FRONT BUMPER FOAM FILLER PIECE	\$	117.00	?
15	FRONT BUMPER COVER	\$	120.00	X
16	CAUTION SIGN STICKER	NEC \$	13.00	X
17	AIRCON STICKER	NEC \$	7.00	X
18	LOCK CARRIER BRACKET	\$	129.00	X
19	LOCK CARRIER BRACKET SUPPORT - LH / RH	\$	54.00	X
20	FRONT PARKING AID SENSOR - FRONT OUTER	\$	TBC	X
SUB TOTAL SPARE PARTS CHARGES		: \$ 7,665.00		

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

SKJ 689E
Material List for Accident Vehicle Regn No. SFE-26-D

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
21	FRONT PARKING AID SEAL RING <i>new</i>	4	\$	14.00 <i>+</i>
22	HORN - LH HIGH TONE <i>?</i>	\$		119.00 <i>?</i>
23	SPRING SHACKLE - LH <i>?</i>	\$		27.00 <i>?</i>
24	WHEEL SPOILER <i>new</i>	\$		69.00 <i>+</i>
25	WHEEL SPOILER TRIM - LH <i>new</i>	\$		36.00 <i>+</i>
26	BONNET <i>Dented</i>	\$		2,682.00 <i>✓</i>
27	BONNET ATTACHMENT PARTS <i>?</i>	\$		116.00 <i>?</i>
28	BONNET IMPACT PROTECTION - LH / RH / CENTRE <i>?</i>	3	\$	78.00 <i>?</i>
29	BONNET STRIKER - LH <i>new</i>	\$		47.00 <i>+</i>
30	BONNET LID LOCK <i>new</i>	\$		202.00 <i>+</i>
31	BONNET BOWDEN CABLE - CENTRE <i>new</i>	\$		54.00 <i>+</i>
32	LED HEADLIGHT - LH <i>new</i>	\$		7,438.00 <i>✓</i>
33	LIFT CYLINDER - LH <i>?</i>	\$		187.00 <i>?</i>
34	RADIATOR AIR GUIDE - LH <i>?</i>	\$		30.00 <i>+</i>
35	RADIATOR AIR GUIDE - LH <i>new</i>	\$		15.00 <i>+</i>
36	RADIATOR AIR GUIDE - UPPER <i>new</i>	\$		15.00 <i>+</i>
37	TEMPERATURE SENSOR BRACKET <i>new</i>	\$		18.00 <i>+</i>
38	FRON NO PLATE <i>new</i>	S/N	\$	60.00 <i>✓</i>
39	SUNDRIES <i>?</i>	\$		300.00 <i>?</i>
TOTAL SPARE PARTS CHARGES		:		\$ 19,172.00
TOTAL LABOUR CHARGES		:		\$ 7,172.00
GRAND TOTAL		:		\$ 26,344.00

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Adrian Lim
02/07/20

Not Authorised, 04 Days.

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	Acknowledged by Repairer Signature: Date:
--	---

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant