

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 39666

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0456/2020/NS
Date : 30-Jun-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

5 days - ok - jb - 25 Jan 21

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Sung Kuang (Song Gang)
Address : Blk 656A Jurong West Street 61
#06-341
Singapore 641656
Telephone : +(65) 96659883
Type of Claim : Own Damage Claims
Policy No. : 1800073873
Vehicle No : **SKJ 689 E**
Model Code : Audi A5 SB 2.0 TFS
Model / Year : Jul-18
Engine No : CVK 064263
Chassis No : WAUZZZF51JA112867
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Jun-20
Place of Accident : Toh Guan Road (IMM Carpark Exit)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKJ 689 E

S/N	Nature of Jobs		Estimated Charges	Surveyor's recommendations
1	To remove and transfer/reinstall front bumper wire harness for front parking aid system.	S/N	\$ 280.00	\$ 280.00
2	To dismantle and renew front bumper, bonnet and lhs headlight. To repair lhs front fender. Re-organise crash management components. Reinstall all parts removed.		\$ 3,200.00	\$ 1,250.00
3	To respray front bumper, lhs front fender and bonnet. <i>(Include LHS frt fender)</i>		\$ 3,500.00	\$ 1,650.00
4	Added labour		\$ 1,000.00	\$ 500.00
5	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 8,172.00	\$ 3,872.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFE 26 D

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 2,142.00	\$ 1,800.80
2	FRONT BUMPER FIXING PARTS	\$ 383.00	
3	FRONT BUMPER SECURING STRIP	2 \$ 34.00	
4	FRONT BUMPER GRILLE - CENTRE	\$ 185.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 215.00	
6	FRONT BUMPER SPOILER	\$ 504.00	
7	FRONT BUMPER AIR GUIDE - LH	\$ 59.00	
8	RADIATOR GRILLE	\$ 2,190.00	
9	SULTRASOUND SENSOR SUPPORT - LH / RH	2 \$ 98.00	
10	RADIATOR GRILLE COVER - UPPER	\$ 178.00	
11	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 446.00	\$ 374.40
12	FRONT BUMPER CARRIER	\$ 757.00	\$ 635.60
13	FRONT BUMPER GUIDE SECTION - LH	\$ 34.00	
14	FRONT BUMPER FOAM FILLER PIECE	\$ 117.00	\$ 98.40
15	FRONT BUMPER COVER	\$ 120.00	
16	CAUTION SIGN STICKER	NEC \$ 13.00	
17	AIRCON STICKER	NEC \$ 7.00	
18	LOCK CARRIER BRACKET	\$ 129.00	\$ 108.40
19	LOCK CARRIER BRACKET SUPPORT - LH / RH	2 \$ 54.00	
20	FRONT PARKING AID SENSOR - FRONT OUTER	TBC	
SUB TOTAL SPARE PARTS CHARGES		\$ 7,665.00	\$ 3,017.60

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFE 26 D

S/N	Parts Description		Damage Parts & Prices	
			S/Nett	Remarks
		<i>c/f</i>		\$ 3,017.60
21	FRONT PARKING AID SEAL RING	4	\$ 14.00	
22	HORN - LH HIGH TONE		\$ 119.00	
23	SPRING SHACKLE - LH		\$ 27.00	
24	WHEEL SPOILER		\$ 69.00	
25	WHEEL SPOILER TRIM - LH		\$ 36.00	
26	BONNET		\$ 2,682.00	\$ 2,253.60
27	BONNET ATTACHMENT PARTS		\$ 116.00	
28	BONNET IMPACT PROTECTION - LH / RH / CENTRE	3	\$ 78.00	\$ 64.88
29	BONNET STRIKER - LH		\$ 47.00	
30	BONNET LID LOCK		\$ 202.00	
31	BONNET BOWDEN CABLE - CENTRE		\$ 54.00	
32	LED HEADLIGHT - LH		\$ 7,438.00	\$ 6,249.60
33	LIFT CYLINDER - LH		\$ 187.00	
34	RADIATOR AIR GUIDE - LH		\$ 30.00	
35	RADIATOR AIR GUIDE - LH		\$ 15.00	
36	RADIATOR AIR GUIDE - UPPER		\$ 15.00	
37	TEMPERATURE SENSOR BRACKET		\$ 18.00	\$ 14.40
38	FRON NO PLATE	S/N	\$ 60.00	\$ 60.00
39	Added parts		\$ 1,210.00	\$ 1,015.68
40	SUNDRIES		\$ 300.00	\$ 17.60
TOTAL SPARE PARTS CHARGES			\$ 20,382.00	\$ 12,693.36
TOTAL LABOUR CHARGES			\$ 8,172.00	\$ 3,872.00
GRAND TOTAL			\$ 28,554.00	\$ 16,565.36

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0456/2020/NS 13-Jul-20 Glory Tan 1 of 1 SKJ 689 E Audi A5 SB 2.0 TFS
Quantity	Description	Unit Price	Amount
Parts			
1	Front fender LHS	\$ 997.00	\$ 838.40
2	Front fender top ledge cover inner LHS	\$ 34.00	\$ 27.92
3	Front fender top ledge cover outer LHS	\$ 15.00	\$ 12.16
4	Front fender emblem trim LHS	\$ 150.00	\$ 125.60
5	Bracket for lift cylliner LHS	\$ 14.00	\$ 11.60
			\$ 1,015.68
Labours			
1	To renew lhs front fender.	\$ 1,000.00	\$ 500.00
TOTAL		\$ 2,210.00	\$ 1,515.68

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant