

ASS. REC. BY:

REP:

CC3/ AIG 20006928 / Avf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 1800073873

Claims No. 8931595365 SG

Sum Insured: _____ Excess: 800

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKJ689E Yr Regn: 2018/ July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Audi A5 SB c.c. 1984

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 29402 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZFS1JA*112867

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40R18

R: 245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Front N

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. 29/6/20 D.O.I. 02/07/20

Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Front N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>OD ALG</u>
<u>3H/20</u>	<u>Revert via merimen</u>
<u>7H/20</u>	<u>Rece approved from Victor via merimen, frt no plate to take out</u>
	<u>MV: 140K</u>
	<u>PV: 62K</u>
	<u>Nett: 78K</u>
<u>7H/20</u>	<u>Informed Terrence c/A ex \$800, frt no plate to take out by email</u>
<u>25/1/21</u>	<u>final fig \$16,565.36 confirmed by email (Reel 11,988.64, 419)</u>

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Date/Time, File Return to?
2) 4/3/21-Typist

Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)

Survey Fee:	
Transportation:	
Photos	
Others	
TOTAL	

Report Format : Merimen
Lump Sum / L.B.I. : \$16,565.36

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 39666

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0456/2020/NS
Date : 30-Jun-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Sung Kuang (Song Gang)
Address : Blk 656A Jurong West Street 61
#06-341
Singapore 641656
Telephone : +(65) 96659883
Type of Claim : Own Damage Claims
Policy No. : 1800073873
Vehicle No : **SKJ 689 E**
Model Code : Audi A5 SB 2.0 TFS
Model / Year : Jul-18
Engine No : CVK 064263
Chassis No : WAUZZZF51JA112867
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Jun-20
Place of Accident : Toh Guan Road (IMM Carpark Exit)

Premium Automobiles

55 Ubi Road 1, Singapore 408695
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKJ 689 E

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer/reinstall front bumper wire harness for front parking aid system.	S/N \$ 280.00	✓ ✓
2	To dismantle and renew front bumper, bonnet and lhs headlight. To repair lhs front fender. Re-organise crash management components. Reinstall all parts removed.	\$ 3,200.00	1250 ✓
3	To respray front bumper, lhs front fender and bonnet.	\$ 3,500.00	1100 1650 ✓
4	To carry out diagnostic check.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: <u>\$ 7,172.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFE-26-D SKJ 689E

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER <i>Defend</i>	\$	2,142.00	✓ 1800.80
2	FRONT BUMPER FIXING PARTS	\$	383.00	X
3	FRONT BUMPER SECURING STRIP	2 \$	34.00	X
4	FRONT BUMPER GRILLE - CENTRE	\$	185.00	X
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$	215.00	X
6	FRONT BUMPER SPOILER	\$	504.00	X
7	FRONT BUMPER AIR GUIDE - LH	\$	59.00	200 ? X
8	RADIATOR GRILLE	\$	2,190.00	X
9	SULTRASOUND SENSOR SUPPORT - LH / RH	2 \$	98.00	X
10	RADIATOR GRILLE COVER - UPPER	\$	178.00	X
11	FRONT BUMPER AIR GUIDE GRILLE - LH	\$	446.00	✓ 374.40
12	FRONT BUMPER CARRIER	\$	757.00	? 1635.60
13	FRONT BUMPER GUIDE SECTION - LH	\$	34.00	X
14	FRONT BUMPER FOAM FILLER PIECE	\$	117.00	? 98.40
15	FRONT BUMPER COVER	\$	120.00	X
16	CAUTION SIGN STICKER	NEC \$	13.00	X
17	AIRCON STICKER	NEC \$	7.00	X
18	LOCK CARRIER BRACKET	\$	129.00	X 108.40
19	LOCK CARRIER BRACKET SUPPORT - LH / RH	2 \$	54.00	X
20	FRONT PARKING AID SENSOR - FRONT OUTER		TBC	X
SUB TOTAL SPARE PARTS CHARGES		:	\$ 7,665.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFE 26-D *SKJ689E*

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	FRONT PARKING AID SEAL RING <i>Not nec</i>	4 \$	14.00 +
22	HORN - LH HIGH TONE <i>Not nec</i>	\$	119.00 ? X
23	SPRING SHACKLE - LH <i>Not nec</i>	\$	27.00 ? X
24	WHEEL SPOILER <i>Not nec</i>	\$	69.00 X
25	WHEEL SPOILER TRIM - LH <i>Not nec</i>	\$	36.00 +
26	BONNET <i>Dented</i>	\$	2,682.00 ✓ 2253.60
27	BONNET ATTACHMENT PARTS <i>Not nec</i>	\$	116.00 ? X
28	BONNET IMPACT PROTECTION - LH / RH / CENTRE <i>Not nec</i>	3 \$	78.00 ? 64.88
29	BONNET STRIKER - LH <i>Not nec</i>	\$	47.00 +
30	BONNET LID LOCK <i>Not nec</i>	\$	202.00 +
31	BONNET BOWDEN CABLE - CENTRE <i>Not nec</i>	\$	54.00 +
32	LED HEADLIGHT - LH <i>Not nec</i>	\$	7,438.00 ✓ 6349.60
33	LIFT CYLINDER - LH <i>Not nec</i>	\$	187.00 ? X
34	RADIATOR AIR GUIDE - LH	\$	30.00 +
35	RADIATOR AIR GUIDE - LH	\$	15.00 +
36	RADIATOR AIR GUIDE - UPPER	\$	15.00 +
37	TEMPERATURE SENSOR BRACKET <i>Not nec</i>	\$	18.00 + 14.40
38	FRON NO PLATE <i>Not nec</i>	S/N \$	60.00 ✓ 60
39	SUNDRIES <i>Not nec</i>	\$	300.00 ? 17.60
TOTAL SPARE PARTS CHARGES		:	\$ 19,172.00
TOTAL LABOUR CHARGES		:	\$ 7,172.00
GRAND TOTAL		:	\$ 26,344.00 <i>28,554</i>

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 02/07/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Veron.

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. PA/OD/0456/2020/NS Date 13-Jul-20 Service Advisor Glory Tan Pages 1 of 1 Regn No SKJ 689 E Model No Audi A5 SB 2.0 TFS	
Quantity	Description	Unit Price	Amount
Parts			
1	Front fender LHS <i>Buckled.</i>	\$ 997.00	✓ 838.40
2	Front fender top ledge cover inner LHS	\$ 34.00	✓ 27.92
3	Front fender top ledge cover outer LHS <i>} Nec</i>	\$ 15.00	✓ 12.16
4	Front fender emblem trim LHS <i>scr</i>	\$ 150.00	✓ 125.60
5	Bracket for lift cylliner LHS <i>cruld</i>	\$ 14.00	✓ 11.60
Labours			
1	To renew lhs front fender.	\$ 1,000.00	500 ✓
TOTAL		\$ 2,210.00	

For Premium Automobiles Pte Ltd

Adrian Lj
13/07/20
add 1 day
ALJ

 Authorised Signature