

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

*Veron.*

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

### Estimate No.

PA/0D/0456/2020/NS

### Date

13-Jul-20

### Service Advisor

Glory Tan

### Pages

1 of 1

### Regn No

SKJ 689 E

### Model No

Audi A5 SB 2.0 TFS

Quantity	Description	Unit Price	Amount
<b>Parts</b>			
1	Front fender LHS <i>Bracket.</i>	\$ 997.00	✓
2	Front fender top ledge cover inner LHS	\$ 34.00	✓
3	Front fender top ledge cover outer LHS <i>} Nec</i>	\$ 15.00	✓
4	Front fender emblem trim LHS <i>new</i>	\$ 150.00	✓
5	Bracket for lift cylliner LHS <i>could</i>	\$ 14.00	✓
<b>Labours</b>			
1	To renew lhs front fender.	<del>\$ 1,000.00</del>	500
TOTAL		\$ 2,210.00	

For Premium Automobiles Pte Ltd

*Adrian Ling*  
*13/07/20*  
*add 1 day*  
*ALG.*

\_\_\_\_\_  
Authorised Signature

# Premium Automobiles

55 (B) Road 1, Singapore 408601  
Tel: 6386 2323 Fax: 6841 118

Telefax

## Estimated Labour Charges for Accident Vehicle SKJ 689 E

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer/reinstall front bumper wire harness for front parking aid system	S/N \$ 280.00 ✓	
2	To dismantle and renew front bumper, bonnet and lhs headlight. To repair lhs front fender. Re-organise crash management components. Reinstall all parts removed. ✓ <del>ik</del> ✓ ✓	\$ <del>3,200.00</del>	1250
3	To respray front bumper, lhs front fender and bonnet.	\$ <del>3,500.00</del>	<del>1100</del> 1650 H.S.
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 7,172.00</b>	

Car - in 13/7/2020

LR/Koong

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

SKJ689E

wip: 39666

4 Lays

Material List for Accident Vehicle Regn No. SFE 26-D

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER <i>Defend</i>	\$	2,142.00 ✓	
2	FRONT BUMPER FIXING PARTS	\$	383.00 x	
3	FRONT BUMPER SECURING STRIP	} <i>Not nee</i>	2 \$ 34.00 x	
4	FRONT BUMPER GRILLE - CENTRE			
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	<i>Ref ne</i>	\$ 185.00 +	
6	FRONT BUMPER SPOILER <i>Ref ne</i>	\$	215.00 +	
7	FRONT BUMPER AIR GUIDE - LH <i>Ref ?</i>	\$	504.00 x	
8	RADIATOR GRILLE <i>Ref ne</i>	\$	59.00 <i>Ref</i>	
9	SULTRASOUND SENSOR SUPPORT - LH / RH <i>Ref ne</i>	\$	2,190.00 +	
10	RADIATOR GRILLE COVER - UPPER <i>Ref ne</i>	\$	98.00 +	
11	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Ref</i>	\$	178.00 +	
12	FRONT BUMPER CARRIER <i>Def</i>	\$	446.00 ✓	
13	FRONT BUMPER GUIDE SECTION - LH <i>Ref ne</i>	\$	757.00 ✓	
14	FRONT BUMPER FOAM FILLER PIECE <i>Defend</i>	\$	34.00 x	
15	FRONT BUMPER COVER <i>Ref ne</i>	\$	117.00 ✓	
16	FRONT BUMPER COVER	\$	120.00 x	
17	CAUTION SIGN STICKER	NEC \$	13.00 +	
17	AIRCON STICKER	NEC \$	7.00 +	
18	LOCK CARRIER BRACKET <i>Ref ne could</i>	\$	129.00 ✓	
19	LOCK CARRIER BRACKET SUPPORT - LH / RH <i>Ref ne</i>	2 \$	54.00 +	
20	FRONT PARKING AID SENSOR - FRONT OUTER <i>Ref ne</i>		TBC +	
<b>SUB TOTAL SPARE PARTS CHARGES</b>		<b>:</b>	<b>\$ 7,665.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1182

Telefax

SKJ689E

Material List for Accident Vehicle Regn No. SFE 26-D

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
21	FRONT PARKING AID SEAL RING <i>Abel m</i>	4	\$ 14.00	+
22	HORN - LH HIGH TONE ?		\$ 119.00	?
23	SPRING SHACKLE - LH ?		\$ 27.00	?
24	WHEEL SPOILER <i>Abel m</i>		\$ 69.00	x
25	WHEEL SPOILER TRIM - LH <i>Abel m</i>		\$ 36.00	x
26	<b>BONNET</b> <i>Dented</i>		\$ 2,682.00	✓
27	BONNET ATTACHMENT PARTS ?		\$ 116.00	?
28	BONNET IMPACT PROTECTION - LH / RH (CENTRE ?) <i>3</i>		\$ 78.00	✓
29	BONNET STRIKER - LH <i>Abel m</i>		\$ 47.00	+
30	BONNET LID LOCK <i>Abel m</i>		\$ 202.00	+
<i>No. 31</i>	<del>BONNET BOWDEN CABLE (CENTRE ?)</del>		\$ 54.00	+
32	LED HEADLIGHT - LH <i>lit</i>		\$ 7,438.00	✓
33	LIFT CYLINDER - LH ?		\$ 187.00	?
34	RADIATOR AIR GUIDE - LH		\$ 30.00	x
35	RADIATOR AIR GUIDE - LH		\$ 15.00	f
36	RADIATOR AIR GUIDE - UPPER <i>Abel m</i>		\$ 15.00	+
37	TEMPERATURE SENSOR BRACKET <i>Abel m</i>		\$ 18.00	✓
38	FRON NO PLATE <i>Nil</i>	S/N	\$ 60.00	✓
39	SUNDRIES ?		\$ 300.00	?
<b>TOTAL SPARE PARTS CHARGES</b>			<b>\$ 19,172.00</b>	
<b>TOTAL LABOUR CHARGES</b>			<b>\$ 7,172.00</b>	
<b>GRAND TOTAL</b>			<b>\$ 26,344.00</b>	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

*lift cylinder bracket*

*4 pop rivet*

*for door.*