



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.

Tel : 6484 1221

Fax : 6484 7829

385 Sin Ming Drive (Inside Vicom) Singapore 575718.

Tel : 6753 2112

Fax : 6451 0394

Co. Reg No. : 200005485N

GST Reg No. : 20-0005485-N

### Repair Estimates

SKT 7939 K

*Not Authorized*  
*Henry Bepaint*

Parts	(a) Cost / List Price Items	\$	2,711.00
	Plus/Less 20%	\$	542.20
	Total of Cost / List	\$	2,168.80
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
	Total Parts Cost		
Labour		\$	1,870.00
Total		\$	4,038.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 3/7/20 at \_\_\_\_\_

#### Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Le Date: 3/7/20





**ESTEEM  
PERFORMANCE**

# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.

Tel : 6484 1221

Fax : 6484 7829

385 Sin Ming Drive (Inside Vicom) Singapore 575718

Tel : 6753 2112

Fax : 6451 0394

Co. Reg No. : 200005485N

GST Reg No. : 20-0005485-N

## Spare Parts

Vehicle No. :

**SKT 7939 K**

Make & Model :

**MAZDA 3**

Chassis No. :

**JM6BM42A8G0312157**

Submit By :

**SHANICE**

Year Manufacture :

**2015**

Engine No. :

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp RH <i>CM</i>	1	\$812.00		✓
2	Front bumper <i>Bu / mgm</i>	1	\$972.00		✓
3	Front bumper clip <i>nc</i>	10	\$5.00		✓
4	Front bumper reinforcement <i>n</i>	1	\$594.00		X
5	Front bumper side retainer LH <i>pu</i>	1	\$20.00		X
6	Front bumper side retainer RH <i>dit</i>	1	\$20.00		✓
7	Front bumper bracket LH <i>n</i>	1	\$16.00		X
8	Front bumper bracket RH <i>n</i>	1	\$16.00		X
9	Front bumper sponge	1	-		
10	Fog lamp RH <i>pu</i>	1	\$166.00		X
11	Fog lamp garnish RH <i>pu</i>	1	\$45.00		X
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.





Blk 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.

Tel : 6484 1221

Fax : 6484 7829

385 Sin Ming Drive (Inside Vicom) Singapore S75718.

**Tel : 6753 2112**

**Fax : 6451 0394**

Co. Reg No.: 200005485N

**GST Reg No. : 20-0005485-N**

Vehicle No. : **SKT 7939 K**

Submit By : Carmen Lim

Make & Model : MAZDA 3

Year of Manufacture : 2015

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*