



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 177A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,985.00	-
10	REAR BUMPER RIVET	NOT NECESSARY	90.00	-
1	REAR BUMPER CHROME TRIM RH	NOT NECESSARY	258.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	2,057.00	-
1	REAR FENDER INNER SHIELD RH	NOT NECESSARY	330.00	-
1	REAR DOOR RH	TO REPAIR SEE LABOUR	2,220.00	-
1	SIDE SKIRT RH	NOT NECESSARY	735.00	-
1	SPORTS RIM	SCRATCHED	1,306.00	1,306.00
1	SPORTS RIM LOGO EMBLEM COVER	NECESSARY	158.00	158.00
1	REAR WHEEL BEARING RH	* CHECK	325.00	-
1	REAR DISC ROTOR RH	NOT NECESSARY	220.00	-
1	REAR ABSORBER RH	NOT NECESSARY	679.00	-
1	REAR ABSORBER MOUNTING RH	NOT NECESSARY	239.00	-
1	REAR KNUCKLE ARM RH	* CHECK	1,550.00	-
1	REAR CAMBER STRUT RH	* CHECK	292.00	-
1	REAR STRUT ROD RH	* CHECK	295.00	-
1	REAR TIE ROD RH	* CHECK	325.00	-
1	REAR TIE ROD END RH	* CHECK	305.75	-
1	REAR THRUST ARM RH	* CHECK	215.00	-
1	REAR THRUST ARM TOP COVER RH	NOT NECESSARY	86.00	-
1	REAR THRUST ARM BOTTOM COVER RH	NOT NECESSARY	90.00	-
	LESS 10% DISCOUNT		-1,376.07	-146.40
			12,384.68	1,317.60
	<u>LABOUR</u>			
	TO REMOVE, REPAIR & INSTALL ALL ACCIDENT AFF. PORTIONS. INCLUSIVE OF THE REPAIR OF REAR BUMPER, REAR FENDER RH AND REAR DOOR RH.		1,000.00	300.00
	TO CHECK ENGINE WARNING LIGHT (ABS, ECU, & ETC.)		350.00	150.00
	TO CHECK ALL NECESSARY WIRING.		230.00	60.00

Report Ref No. CC4/FCI20006943/R1ds3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	150.00	80.00
	TO PUTTY & RESPRAY ALL ACCIDENT AFF. PORTIONS.		1,200.00	750.00
	TO APPLY ANTI-RUST COATING ON ALL ACCIDENT AFF. PORTIONS.		120.00	-
			3,050.00	1,340.00
GRAND TOTAL			15,434.68	2,657.60
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$2,976.98 NETT)				2,657.60

Report Ref No. CC4/FCI20006943/R1ds3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.