

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. Reg. No. : 200820153N

Date : 02 / 07 / 2020

ESTIMATE COSTS OF REPAIR

M/s Andric Leasing

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

Dear Sir / Madam ,

Vehicle no. : SLV 4215 M - Toyota Prius Hybrid 1.8E CVT

Accident date : 02 / 07 / 2020

*Not Authorized
C/Sing @ 3600k
Return After Repair
4 days*

Quantity	Descriptions	Amount (S\$)
1	1 pc tail gate <i>1147.80</i>	<i>Sn</i> \$ 1,211.40 ✓
2	1 pc tail gate 'Toyota' logo	\$ <i>Sn</i> 60.30 ✓
3	1 pc tail gate 'PRIUS' emblem	\$ <i>Sn</i> 65.60 ✓
4	1 pc tail gate Hybrid Synergy Drive emblem	\$ <i>Sn</i> 51.90 ✓
5	1 pc tail gate inner lock	\$ <i>X</i> 472.45 X
6	1 pc tail gate inner lock catch	\$ <i>X</i> 48.90 X
7	1 pc tail gate garnish <i>925.60</i>	\$ <i>CM</i> 960.00 ✓
8	1 pc tail gate inner trim	\$ <i>Sn</i> 568.00 X
9	1 pc rear weather-strip	\$ <i>Sn</i> 353.40 X
10	1 pc o/s tail lamp top	\$ <i>Sn</i> 501.30 X
11	1 pc o/s tail lamp bottom	\$ <i>Sn</i> 486.20 ✓
12	1 pc rear bumper top <i>458.60</i>	\$ <i>Sn</i> 1,358.50 ✓
13	1 pc rear bumper bottom <i>576.30</i>	\$ <i>Sn</i> 946.20 ✓
14	2 pcs rear bumper side cover 1 @ 188.00 <i>123.70</i>	<i>CM</i> \$ 376.00 ✓
15	1 pc o/s rear bumper lower cover (side)	<i>Sn</i> \$ 112.00 X
16	1 pc n/s rear bumper lower cover (side)	\$ <i>Sn</i> 115.00 X
17	1 pc rear bumper lower cover (center)	<i>CM</i> \$ 183.00 ✓
18	2 pcs rear bumper side retainer 1 @ 94.80	\$ <i>Sn</i> 189.60 X
19	2 pcs rear bumper bracket 1 @ 87.10	\$ <i>X</i> 174.20 X
20	1 pc rear bumper tow cover	\$ <i>Sn</i> 67.90 X
21	1 pc rear bumper reinforcement <i>398.80</i>	\$ <i>By</i> 507.20 ✓
		\$ 8,809.05
	Less 25%	\$ 2,202.26
		\$ 6,606.79
2	1 pc rear no. plate	\$ <i>Sn</i> 100.00 sn X
3	2 pcs rear windscreen glass inner seal 1 @ 60.00	\$ <i>Sn</i> 120.00 sn <i>60.00</i>
4	2 pcs rear windscreen glass gum 1 @ 60.00	\$ <i>Sn</i> 120.00 sn <i>80.00</i>
5	1 set rear reverse sensor	\$ <i>Sn</i> 350.00 sn X
	Balance C/FD	\$ 7,296.79

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. Reg. No. : 200820153N

Balance B/FD (SLV 4215 M)	\$	7,296.79	
Labour charges	\$	1,600.00	500
To putty and spray painting	\$	1,400.00	600
Re-seal anti rust	~ \$	200.00	X
To check ,repair wiring	\$	120.00	20
To transfer tail gate	\$	120.00	60
To remove and refix rear both windscreen glass	\$	220.00	180
	\$	10,956.79	
Plus : 7% GST	\$	766.98	
Grand total	\$	11,723.76	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: