



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877 Contact No	Cust No/Name	/Mr Ng Soh Seng
	Reg No/Reg Date	SLQ4759L / 12/07/2017
	Date In/Mileage	13/07/2020/ 58248
	Chassis No	KNAFX411MH5721032
	Engine No	G4FGGH638296
	Make/Model	KIA/CERATO K3 1.6 A EX BWY
	Colour/Trim	MST / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
F0000034	Credit	18/07/2020/ 09:35	DS	218 / MarsLer	47787				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
S	MIPNT88088								280.00
	REVERSE SENSOR SET								
M	SUNDRY								50.00
	C & C LOGO								
S	MIPNT88088								250.00
	DIAGNOSTIC / SCANNING								
S	MIPNT88088								80.00
	TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS								
S	MIPNT88088								300.00
	TO REMOVE AND RE-INSTALL TRIMMING AND CAPERTING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS								
S	MIPNT88088								1200.00
	TO REPLACE REAR BUMPER,ETC								
	-TO REPAIR REAR END PANEL AND LHR OTR QTR PNL AND TRUNK LID STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS								
S	MIPNT98088								1680.00
	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS								
X	KS 86611 A7 800	COVER - REAR BUMPER	1.00	688.00	0.00	688.00			
M	KS 86695 A7 800	COVER - REAR BUMPER,	1.00	347.00	0.00	347.00			
X	KS 92405 A7 500	LH REFLECTOR REFLEX	1.00	99.00	0.00	99.00			
M	KS 0G032 50 037A	CLIP - BUMPER	10.00	2.00	0.00	20.00			
X	KS 86613 A7 001	LH SIDE BRACKET - RE	1.00	29.00	0.00	29.00			
X	KS 86310 A7 050	KIA SUB LOGO ASSY	1.00	37.00	0.00	37.00			
X	KS 86311 A7 030	EMBLEM - CERATO	1.00	35.00	0.00	35.00			
X	WFEMBLEMK3	EMBLEM K3	1.00	15.00	0.00	15.00			
Z	NOTES								
	ACCIDENT ON 02/07/2020 ALONG NEW UPPER CHANGI RD TWD BEDOK MRT STATION								
	OWNER CLAIMING THIRD PARTY								
	REQUIRED REPLACEMENT CAR (R/A-22669)								
	TP # SHD3008T TP INS : MS FIRST CAPITAL								

Confirm & accepted by

Parts	1,270.00
Labour	0.00
Standard Menu	0.00
Specialist Job	3,790.00
Others(Lub,etc)	0.00
Sundry	50.00
Total(w/o GST)	5,110.00

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.