



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL  
(BUDGET DIRECT INSURANCE)  
190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRE  
SINGAPORE 239924

INV No. AC2005095  
INV Date 21/07/2020  
Reference CS/AGI20006963/Ayf3n2  
Code AGI



#### PROFESSIONAL SERVICE FEE

Vehicle No. SKC 1494E  
Insured Veh. SLC 994Z  
Claim No. C10006634  
Policy No.  
Accident Date 03/07/2020  
Inspection Date 06/07/2020

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL Ref : CS/AGI20006963/Ayf3n2

(BUDGET DIRECT INSURANCE)  
190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRESINGAPORE  
239924

Date : 21-07-2020



Code : AGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLC 994Z	<b>Veh. Inspected</b>	SKC 1494E
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	C10006634	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	IVY RATILLA	<b>Assign Date</b>	03/07/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	VOLKSWAGEN PASSAT CC	<b>c.c</b>	1798
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2011
<b>Chassis No.</b>	WVWZZZ3CZCE517738	<b>Colour</b>	BLACK
<b>Odometer</b>	84125	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	235/45 R17	GOODYEAR	6 mm
<b>L/H Front Tyre</b>	235/45 R17	GOODYEAR	6 mm
<b>R/H Rear Tyre</b>	235/45 R17	GOODYEAR	6 mm
<b>L/H Rear Tyre</b>	235/45 R17	GOODYEAR	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	03/07/2020	<b>Inspection Date</b>	06/07/2020
<b>Survey held at</b>	POLYMATH GARAGE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-02 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 1494E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR RH DOOR	DENTED	1,685.00	1,685.00
1	REAR RH DOOR LOCK	DAMAGED	298.00	298.00
1	REAR RH DOOR WEATHERSTRIPE	NECESSARY	325.00	325.00
1	REAR RH DOOR OUTER HANDLE	CUT	458.00	458.00
1	REAR RH DOOR LOWER CHROME MOULDING	CUT	231.00	231.00
1	REAR RH DOOR INNER TRIM BOARD	NOT NECESSARY	1,477.00	-
1	REAR RH DOOR INNER TRIM BOARD CLIPS	NOT NECESSARY	50.00	-
1	REAR RH DOOR REGULATOR GEAR	NOT NECESSARY	395.00	-
1	REAR RH FENDER	TO REPAIR SEE LABOUR	1,348.00	-
1	REAR RH SHOCK ABSORBER	NOT NECESSARY	452.00	-
1	REAR RH LOWER ARM	NOT NECESSARY	470.00	-
1	REAR RH WHEEL HUB C/W BEARING	DAMAGED	385.00	385.00
1	REAR RH KNUCKLE ARM	NOT NECESSARY	1,007.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,109.00	-
1	REAR BUMPER CLIPS	NOT NECESSARY	50.00	-
1	REAR BUMPER SIDE HOLDER RH	NOT NECESSARY	58.00	-
1	REAR BUMPER CHROME MOULDING	NOT NECESSARY	351.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	135.00	-
	LESS 5% DISCOUNT		-	-169.10
			10,284.00	3,212.90
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR RH WHEEL RIM (SN)	CUT	1,200.00	700.00
1	REAR RH TYRE (SN)	NOT NECESSARY	480.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
			1,740.00	700.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR RH FENDER AND REAR BUMPER.		800.00	500.00
	SPRAY PAINTING.		800.00	600.00

Report Ref No. CS/AGI20006963/Ayf3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING.		50.00	30.00
	TO REMOVE UPHOLSTERY.		150.00	60.00
	TO REMOVE REVERSE SENSOR.	NOT NECESSARY	100.00	-
	TO REMOVE REAR WINDSCREEN.	NOT NECESSARY	180.00	-
	TO TRANSFER DOOR FITTINGS.		150.00	80.00
	TO PERFORM WHEEL ALIGNMENT.		150.00	80.00
	TO DISMANTLE REAR UNDERCARRIAGE.		380.00	60.00
			2,760.00	1,410.00
	<b>GRAND TOTAL</b>		<b>14,784.00</b>	<b>5,322.90</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,000.00</b>

Report Ref No. CS/AGI20006963/Ayf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKC 1494E

INSPECTION






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKC 1494E

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKC 1494E

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

