

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 40257

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0469/2020/NS
Date	:	6-Jul-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Fang Haijun
Address	:	Blk 470 Jurong West Street 41 #06-441 Singapore 640470
Telephone	:	HP +65 81632118
Type of Claim	:	Own Damage Claim
Policy No.	:	1800022532-01
Vehicle No	:	SLW 9687 X
Model Code	:	Audi A3 Sedan 1.0 TFSI 8V
Model / Year	:	Mar-18
Engine No	:	CHZ 652949
Chassis No	:	WAUZZZ8V5J1046143
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	3-Jul-20
Place of Accident	:	Hwa Chong Institution

Premium Automobiles

55 Ulu Road 1, Singapore 408699
Tel: 6366 2523 Fax: 6641 1181

Telefax

Estimated Labour Charges for Accident Vehicle. SLW 9687 X

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer both headlights control units and power modules. To carry out calibration	S/N \$ 700.00 X	
2	To dismantle and renew front bumper and bonnet. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00 500	\$500
3	To respray front bumper and bonnet	\$ 2,000.00 1100	\$1100
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	\$192
SUB TOTAL LABOUR CHARGES		: <u>\$ 4,992.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 9687 X

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>aband</i>	\$ 1,894.00 ✓	\$1515.20
2	FRONT BUMPER FIXING PARTS <i>neu</i>	\$ 176.00 X	
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>neu</i> 2	\$ 72.00 X	
4	FRONT BUMPER GRILLE - CENTRE <i>aband</i>	\$ 151.00 ✓	\$120.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>neu</i>	\$ 505.00 +	\$424.00
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>neu</i> 2	\$ 560.00 +	
7	FRONT BUMPER COVER TRIM - LH / RH <i>neu</i> 2	\$ 306.00 X	
8	WHEEL HOUSING LINER ADAPTER - LH <i>neu</i>	\$ 36.00 X	
9	RADIATOR GRILLE <i>aband</i>	\$ 1,338.00 ✓	\$1070.40
10	RADIATOR GRILLE CLOSING ELEMENT ?	\$ 180.00 ?	\$143.60
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>neu</i> 2	\$ 354.00 X	
12	FRONT BUMPER SIDE REINFORCEMENT BEAM ?	\$ 681.00 ?	
13	FRONT BUMPER FOAM FILLER PIECE ?	\$ 178.00 ?	
14	FOAM FILLER PIECE COVER ?	\$ 115.00 ?	
15	AIRCON STICKER <i>filler</i>	NEC \$ 7.00 ✓	\$5.36
16	CAUTION SIGN STICKER	NEC \$ 13.00 ✓	\$10.24
17	SIGNAL HORN RETAINER - LH HIGH TONE <i>neu</i>	\$ 188.00 X	
18	TEMPERATURE SENSOR BRACKET ?	\$ 18.00 ?	
19	BONNET <i>Repair</i>	\$ 2,988.00 X	
20	BONNET ATTACHMENT PARTS <i>neu</i>	\$ 155.00 X	
SUB TOTAL SPARE PARTS CHARGES		: \$ 9,915.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 9687 X

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/Nett</u>	<u>Remarks</u>
21	BONNET CATCH HOOK	\$ 84.00	X
22	BONNET STRIKER - LH / RH	2 \$ 208.00	X
23	BONNET EDGE PROTECTION	\$ 26.00	X
24	BONNET CATCH HOOK	\$ 60.00	X
25	BONNET LID LOCK	2 \$ 403.00	X
26	LED HEADLIGHT - LH / RH	2 \$ 10,386.00	X
27	LIFT CYLINDER - LH / RH	2 \$ 268.00	X
28	LIFT CYLINDER HOSE	\$ 64.00	X
29	RADIATOR AIR GUIDE - LH / RH	2 \$ 46.00	X
30	RADIATOR AIR GUIDE - UPPER CENTRE	\$ 12.00	X
31	FRONT NO PLATE	S/N \$ 60.00	✓ \$60.00
32	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		: \$21,832.00	
TOTAL LABOUR CHARGES		: \$ 4,992.00	
GRAND TOTAL		: \$26,824.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax 6841 1183

Telefax

Name : Adam King
Surveyed Date : 07/07/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant