



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 4367K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT O/S HEADLAMP	DAMAGED	950.53	816.00
1	FRONT GRILLE	INTACT	682.65	-
1	FRONT BUMPER	DAMAGED	1,487.26	980.00
1	FRONT BUMPER O/S BRACKET	SERVICEABLE	426.50	-
1	FRONT BUMPER O/S FOG LAMP	SERVICEABLE	320.00	-
1	FRONT O/S DOOR	DAMAGED	2,632.86	1,605.00
1	FRONT O/S DOOR RUBBER	SERVICEABLE	125.30	-
1	FRONT O/S DOOR SIGNAL LAMP	DAMAGED	86.95	86.95
1	O/S WHEEL ARCH PANEL GARNISH	DAMAGED	289.62	289.62
1	O/S STEP PANEL GARNISH	DAMAGED	425.00	425.00
	LESS 10% DISCOUNT		-742.67	-420.26
			6,684.00	3,782.31
<u>SPECIAL NETT ITEMS</u>				
1	FRONT O/S DOOR COMPANY STICKER (SN)	NECESSARY	450.00	200.00
1	FRONT O/S WHEEL RIM (SN)	SERVICEABLE	500.00	-
1	FRONT O/S TYRE (SN)	SERVICEABLE	400.00	-
			1,350.00	200.00
<u>LABOUR</u>				
	TO CHECK WIRING, LIGHTING AND RESETTING HEADLAMPS FOCUSING.		80.00	30.00
	TO REMOVE AND REFIT DOORS COMPLETE FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR.		150.00	50.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		100.00	30.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT.		1,080.00	400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	400.00
			2,410.00	910.00
GRAND TOTAL			10,444.00	4,892.31
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,900.00

Report Ref No. CS3/ASM20003122/Eyf3e2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.